Rudder control malfunction, Boeing 757-200ER, September 13, 1993

Micro-summary: This Boeing 757-200ER experienced a rudder control malfunction on climb.

Event Date: 1993-09-13 at 0855 EDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board	NTSB	ID: BFO93IA17	 5	Aircraft Registration Number: N757NA				
FACTUAL REPERT		rence Date: 09/13		 	Most Critical Injury: None			
ÄVIATION	rence Type: Incid	ent	Investigated By: NTSB					
Location/Time	•							
Nearest City/Place	State	Zip Code	Local Time	Time Zone				
JAMAICA	NY	11430	0855	EDT				
Airport Proximity: Unknown	Airport Proximity: Unknown Distance From La			Direction From Airport:				
Aircraft Information Summary								
Aircraft Manufacturer	Model/Serie	s			Type of Aircraft			
BOEING	757-200EF	₹		Airplane				
Sightseeing Flight: No	Air Medical Ti	ir Medical Transport Flight: No						

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On September 13, 1993, about 0855 hours eastern daylight time, N757NA, a Boeing 757-200ER, operating as North American Airlines Flight 5, had a flight control problem during cruise flight. The flight had departed from John F. Kennedy International Airport (JFK), Jamaica, New York, en route to San Francisco, California, but returned to JFK and landed uneventfully. None of the eight crewmembers or 77 passengers were injured. Visual meteorological conditions prevailed and an instrument flight rules flight plan was filed. The flight was conducted under 14 CFR 121.

According to a FAA aviation safety inspector, a "rudder ratio" warning message was displayed in the cockpit as the airplane climbed through Flight Level 270 after departure. The crew performed the published company troubleshooting procedures, including resetting the rudder ratio circuit breaker light, and the warning was eliminated. About one hour later during cruise flight at Flight Level 350, the warning was displayed once again followed by gradual uncommanded right rudder movement. The autopliot was engaged at the time and two units of left aileron were inputted by the autopilot. The airplane remained under control and the crew counteracted the rudder movement manually. The captain elected to abort the flight and return to JFK.

An examination of the airplane's electrical system revealed that the fault ball on right rudder control module had popped out. The module was reset and successfully passed a functional check. The airplane was placed back into service.

The rudder ratio warning message was again displayed on two flights subsequent to this event. The flights terminated uneventfully. According to company maintenance records, maintenance activities to correct the situation during these events involved readjustment of the rigging, functional testing of the fault module, and replacement of the rudder ratio actuator. The airplane was placed back into service after each of these events.

On November 19, 1993, the rudder ratio light was displayed for the fourth time in about two months. An examination of the left yaw damper module revealed a malfunction in the left hydraulic pressure switch. The unit was removed and replaced. No further incidents involving a rudder ratio problem were reported.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: BFO93IA175

Occurrence Date: 09/13/1993

				23, 10, 1000										
AVIATION		Occu	Occurrence Type: Incident											
Landing Facility/Approach In	formation													
Airport Name			Airport ID:	Airport Eleva	ation	Run	way Used	ed Runway Length			Runv	vay Width		
				F	. MSL	. 0								
Runway Surface Type:														
Runway Surface Condition:														
Type Instrument Approach:														
VFR Approach/Landing:														
Aircraft Information														
Aircraft Manufacturer BOEING				el/Series -200ER					Serial 2456	Numbe 7	r			
Airworthiness Certificate(s): Trans	port	<u> </u>												
Landing Gear Type: Retractable - Tricycle														
Homebuilt Aircraft? No	Number of Seats: 2	233	Certif	ied Max Gross \	250000 LBS Number			er of Engines: 2		: 2				
Engine Type: Turbo Fan	9 7.					Engine Manufacturer: Model/Series: Rolls-Royce RB211-535E4						Rated Power:		
- Aircraft Inspection Information														
Type of Last Inspection			Date of Last Inspection Time Sir				nce Last Insp	Airfran	ne To	tal Time				
Continuous Airworthiness			08/1993	08/1993				184 Hours			10	274 Hours		
- Emergency Locator Transmitter (ELT) Information													
ELT Installed? Yes	ELT Operate	ed?		ELT Aided in Locating Accident Site?										
Owner/Operator Information														
Registered Aircraft Owner			Street Address 3800 HOWARD HUGHES PWY, 7TH FL											
ANSETT WORLDWIDE AVIAT	TION, USA		City	City								Zip Code		
			LAS VEGAS								NV 89109			
Operator of Aircraft			Street Address BLDG. 75, JFK AIRPORT											
NORTH AMERICAN AIRLINES	3		City							Stat	е	Zip Code		
			JAMAICA						NY		11430			
Operator Does Business As:						0	perator Desig	nator Co	ode: NC	CA				
- Type of U.S. Certificate(s) Held:	Flag Camian/Dam													
Air Carrier Operating Certificate(s):	Flag Camer/Don	iestic												
Operating Certificate:				Operator	Certific	cate:								
Regulation Flight Conducted Under	r: Part 121: Air Ca	rrier												
Type of Flight Operation Conducted	: Scheduled; Don	nestic;	Passeng	er/Cargo										
	I	FACTU	JAL REP	ORT - AVIAT	ION							Page 2		

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: BFO93IA175

Occurrence Date: 09/13/1993

AVIATION TYBOR	Occurrence Type: Incident														
First Pilot Information			•					'							
Name					City					State) (Date of Birth	Age		
On File					On File	ïle					ile	On File	50		
Sex: M Seat Occupied:	Left	Prir	ncipal Profes	sion: Civilia	n Pilot	ot Certificate Number: On File									
Certificate(s): Airline	ial														
Airplane Rating(s): Multi-	Airplane Rating(s): Multi-engine Land; Single-engine Land														
Rotorcraft/Glider/LTA: None															
Instrument Rating(s): Airplane															
Instructor Rating(s): None)														
Type Rating/Endorsement for Accident/Incident Aircraft? Yes Current Biennial Flight Review?															
Medical Cert.: Class 1	Medica	l Cert. Status	S: Valid Me	dicalno wa	aivers/li	m.		D	ate of La	ast Med	dical Ex	xam: 07/1993	93		
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	t	Actual	Instrument ual Simulat		Ro	otorcraft	Glider	Lighter Than Air		
Total Time	19300	2300													
Pilot In Command(PIC)		2290													
Instructor	3000														
Last 90 Days	150	150													
Last 30 Days	50	50						_							
Last 24 Hours	4	4			<u> </u>										
Seatbelt Used? Yes	Shou	Ider Harness	Used? Yes			Toxico	ology Pe	rforme	d? No		Se	cond Pilot? Ye	es .		
Flight Plan/Itinerary															
Type of Flight Plan Filed: IFF															
Departure Point					Т	State	Т	Airport Identif		or Dopartu		ture Time	Time Zone		
Same as Accident/Incider	nt Location					State		JFK		0455		ture rime	EDT		
Destination						State		Airport Identifier		r					
SAN FRANCISCO							CA SFO								
Type of Clearance: IFR							<u> </u>								
Type of Airspace: Class A	A; Class E														
Weather Information															
Source of Briefing:															
Method of Briefing:															
			FACTUAL	REPORT	- AVIA	TION	N						Page 3		

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: BFO93IA175

Occurrence Date: 09/13/1993

Occurrence Type: Incident

	ETYBOR		l Occ	currence i	ype: ı	incident									
Weather	Weather Information														
WOF ID	Observation Time	Time Zone	WOF	Elevation		WOF Dis	NOF Distance From Accident Site Direction Fro						rom Accident Site		
JFK	0850	EDT		13 Ft. MS	SL				0 NM		0 Deg. Mag.				
Sky/Lowes	et Cloud Condition: Scatt	ered				10	0000 Ft. AG	L	Condition of Light: Day						
Lowest Ce	iling: Broken		130	00 Ft. AG	L	Visibil	lity:	15	SM	Altimeter: 30.00			"Hg		
Temperatu	ıre: 22 °C I	Dew Point:	1	4 °C V	Vind D	Direction:	230			Dei	nsity Altitude:		Ft.		
Wind Spee	ed: 11	Gusts:		v	/eath	er Condti	ons at Accid	lent S	ite: Visual C	Cond	itions				
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0 S	М	Intensity	of Precipita	ation: I	Unknown						
Restrictions to Visibility: None															
Type of Precipitation: None															
Accident Information															
Aircraft Dar	mage: None		Airc	raft Fire: N	lone	e Aircraft Explo					n None				
Classificati	on: U.S. Registered/U	.S. Soil													
- Injury Su	mmary Matrix	Fatal	Serious	Minor	N	None	TOTAL								
First Pi	lot					1	1								
Second	d Pilot					1	1								
Studen	t Pilot				\top										
Flight In	nstructor														
Check	Pilot														
Flight E	ngineer														
Cabin A	Attendants					6	6								
Other C	Crew														
Passen	gers					77	77								
- TOTAL A	ABOARD -					85	85								
Other C	Ground	0	0		0		0								
- GRAND	TOTAL -	0	0		0	85	85								

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: BFO93IA175

Occurrence Date: 09/13/1993

Occurrence Type: Incident

	rativ			

Investigator-In-Charge (IIC)

JEFFREY B. GUZZETTI,

Additional Persons Participating in This Accident/Incident Investigation:

LOU ZABBIA

FAA; 181 S. FRANKLIN AVENUE VALLEY STREAM, NY 11582