In-flight upset due to unexpected seat movement, McDonnell Douglas MD-11, June 29, 1994

Micro-summary: The unexpected movement of the first officer's seat by the other pilot caused the control column to be moved, the autopilot disconnected, a violent upset, and injuries to the airplane's occupants.

Event Date: 1994-06-29 at 0023 EDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

NTSB ID: MIA94FA169

Aircraft Registration Number: N1752K

Occurrence Date: 06/29/1994

Most Critical Injury: Serious

Occurrence Type: Accident

Investigated By: NTSB

Location/Time

Nearest City/Place
CARIBBEAN
CB
Zip Code
Local Time
0023
EDT

Airport Proximity: Off Airport/Airstrip
Distance From Landing Facility:
Direction From Airport:

Aircraft Information Summary

Aircraft Manufacturer Model/Series Type of Aircraft

MCDONNELL DOUGLAS MD-11 Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

HISTORY OF THE FLIGHT

On June 29, 1994, about 0023 eastern daylight time, a McDonnell-Douglas MD-11, N1752K, registered to American Airlines, Inc., operating as American Airlines flight 901, experienced altitude deviation in cruise flight over the Caribbean Sea just south of the Cuban coast, resulting in injuries to passengers and crew. The flight was a 14 CFR Part 121 scheduled international passenger flight from Miami, Florida, to Buenos Aires, Argentina. Visual meteorological conditions prevailed at the time and an instrument flight rules flight plan was filed. The airplane received minor damage. One passenger and 1 flight attendant received serious injuries, 12 passengers and 3 flight attendants received minor injuries, and 67 passengers and 10 flight attendants were not injured. The airline transport-rated captain, first officer, and reserve first officer were not injured. The flight originated at Miami, Florida, on June 28, 1994, at 2333.

The flightcrew stated the captain was in the main cabin taking a rest period. They were in cruise flight and the seatbelt sign was off. Passengers had been requested to keep their seatbelts on when seated. The reserve first officer occupied the captain's seat and the regular first officer was flying the airplane from the right seat. A flight attendant entered the cockpit with a container of beverages. The reserve first officer instructed her to place the container on the footrest of the center observer's seat.

The reserve first officer noticed the flight attendant was having trouble doing this and realized the first officers seat was in the way. The reserve first officer reached across the cockpit and activated the horizontal movement switch of the first officer's seat, without his knowledge, to move it forward out of the flight attendant's way. The first officer had his legs crossed behind the control column and as his seat was moved forward his legs pushed forward on the column. The autopilot turned off and the aircraft responded to the forward control column input and nosed down. The first officer then took the aircraft controls and returned the aircraft to level flight.

The captain returned to the cockpit and the flight attendants reported that some unrestrained passengers and flight attendants had been injured when the aircraft nosed over. The captain instructed the first officer to continue toward Kingston, Jamaica for a possible landing. The captain contacted American Airlines flight dispatch and it was determined that emergency assistance was not available in Kingston, for they could not reach anyone on the phone. The captain then elected to return to Miami, Florida, where the aircraft landed at 0205.

PERSONNEL INFORMATION

Information on the three flight crewmembers is contained in this report under Pilot Information, and in attachments to this report.

NTSB ID: MIA94FA169

Occurrence Date: 06/29/1994

Occurrence Type: Accident

Narrative (Continued)

AIRCRAFT INFORMATION

Information on the aircraft is contained in this report under Aircraft Information.

METEOROLOGICAL INFORMATION

Visual meteorological conditions prevailed at the time of the accident. Additional meteorological information is contained in this report under Weather Information, and in attachments to this report.

FLIGHT RECORDERS

The cockpit voice recorder continued to operate after the accident and recordings for the time of the accident were recorded over after thirty minutes.

Readout and evaluation of the digital flight data recorder from N1752K was performed by Thomas R. Jacky, Aerospace Engineer, NTSB, Washington, D.C. Readout information indicated the aircraft was at an altitude of 33,000 feet, on a heading of 159 degrees, and at position of 20.58 degrees north and 78.50 degrees west, at the time of the accident. About 800 feet of altitude was lost during the nose over and the occupants were subjected to a minimum of -0.37 G's and a maximum of +1.85 G's. See attached Factual Report of Investigation Digital Flight Data Recorder.

MEDICAL AND PATHOLOGICAL INFORMATION

One passenger received serious internal injuries as a result of the altitude deviation. One flight attendant received a serious rib injury as a result of the altitude deviation. The remainder of the passengers and flight attendants who reported injuries sustained minor cut, contusion, and strain injuries.

About 5 hours after the accident the three flight members submitted to toxicology testing in accordance with the American Airlines drug and alcohol testing program. The tests were negative for drugs and alcohol. (See attached toxicology reports.)

ADDITIONAL INFORMATION

The aircraft was released to American Airlines on June 29, 1994, at 0530. The flight data recorder and cockpit voice recorder, which was retained by NTSB after the accident, was returned to American Airlines in September 1994.

NTSB ID: MIA94FA169

Occurrence Date: 06/29/1994

AVIATION			Occurrence Type: Accident										
Landing Facility/Approach Information													
Airport Name Ai				D: /	Airport Elevati	ion	n Runway Used Ru			Runway Length		Runw	ay Width
					Ft.	MSL	0						
Runway Surface Type:													
Runway Surface Condition:													
Type Instrument Approach:													
VFR Approach/Landing: None													
Aircraft Information													
Aircraft Manufacturer MCDONNELL DOUGLAS											Serial Number 48421		
Airworthiness Certificate(s): Transport													
Landing Gear Type: Retractable	- Tricycle												
Homebuilt Aircraft? No	Certi	Certified Max Gross Wt.					618000 LBS Numbe			r of Engines: 3			
Engine Type: Turbo Fan	Engine GE	Engine Manufacturer: Model/Ser CF680C									d Power: 00 LBS		
- Aircraft Inspection Information													
Type of Last Inspection	Date of L	Date of Last Inspection Time Sin				nce Last Inspe	Airfram	Airframe Total Time					
AAIP								Hours 1252				522 Hours	
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? Yes	ELT Operat	ed? No				ELT	Aided in	n Locating Ac	cident S	ite?			
Owner/Operator Information													
Registered Aircraft Owner Street Address P.O. BOX 619616													
AMERICAN AIRLINES, INC.	City							State		Zip Code			
			DFW AIRPORT TX Street Address										75216
Operator of Aircraft	Same as Reg'd Aircraft Owner												
Same as Reg'd Aircraft Owner	City							State	9	Zip Code			
Operator Does Business As:		Operator Designator Code: AALA											
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s)	: Flag Carrier/Don	nestic											
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 121: Air Carrier													
Type of Flight Operation Conducted	d: Scheduled; Inte	ernation	nal; Pass	senge	er Only								
		FACTU	JAL REI	POR'	Γ - AVIATIO	ON							Page 2

NTSB ID: MIA94FA169

Occurrence Date: 06/29/1994

	AVIATI	Occurrence Type: Accident					1										
First Pilot	Information								•								
Name	City					State		Date of Birth	Age								
On File On Fil								le				ile	On File	58			
Sex: M Seat Occupied: Rear Principal Profession: Civilian Pilot									t Certificate Number: On File								
Certificate(s): Airline Transport																	
Airplane Ra	ating(s): Multi	i-engine Lar	nd; Single-e	ngine Land	l												
Rotorcraft/0	Glider/LTA: None	e															
Instrument Rating(s): Airplane																	
Instructor R	Rating(s): None	е															
Type Rating/Endorsement for Accident/Incident Aircraft? Yes Current Biennial Flight Review?																	
Medical Ce	rt.: Class 1	Medica	al Cert. Statu	s: Valid Me	dicalw/ wa	aivers/lii	m.		Da	e of La	st Med	ical Ex	(am: 02/1994				
- Flight Time Matrix All A/C This Make and Model s				Airplane Single Engine	Airplane Mult-Engine	Night		Actual	Instrument Simulated		Rotorcraft		Glider	Lighter Than Air			
Total Time 20000 800																	
Pilot In Con	nmand(PIC)																
Instructor																	
Last 90 Day	/S																
Last 30 Day		64	64		64						_						
Last 24 Hou		3	3		3	<u> </u>	T	D		2.14		10.	I D'I - 10 A				
Seatbelt Us	sed? Yes	Shou	llder Harness	Used?			IOXICO	ology Pe	тогтеа	? Yes		Sec	cond Pilot? Ye	9 S			
Flight Pla	n/Itinerary																
Type of Flig	ht Plan Filed: IF	 R															
Departure F	Point					Т	State	. /	Airport Identifie		r Departur		ture Time	Time Zone			
MIAMI	_						FL		KMIA		2333			EDT			
Destination							State	, ,	Airport Identifier								
BUENOS AIRES								SAEZ									
Type of Cle	arance: IFR																
Type of Airs	space: Class	E															
Weather	Information																
Source of I		ercial Weat	her Service														
Method of	Briefing:																
				FACTUAI	L REPORT	- AVIA	TIOI	N						Page 3			

NTSB ID: MIA94FA169

Occurrence Date: 06/29/1994

Occurrence Type: Accident

Weather	Information														
WOF ID	Observation Time	Time Zone	WOF	Elevation	1	WOF Distance From Accident Site					Direction From Accident Site				
MKJ	0100	EDT		10 Ft. M	1SL				200 NM		160 Deg. Mag.				
Sky/Lowes	st Cloud Condition: Sca	ttered				2	200 Ft. AG	L	Condition of Light: Night/Dark						
Lowest Ce	eiling: None		0 Ft. A	GL	Visibil	lity:	7	SM A		meter:	29.00	"Hg			
Temperatu	ure: 28 °C	2	23 °C	°C Wind Direction: Variable Density Altitude: 1000								Ft.			
Wind Spee	ed: Light and Variable	Gusts:			Weather Condtions at Accident Site: Visual Conditions										
Visibility (F	RVR): 0 Ft	. Visibility	(RVV)	0	SM	Intensity	of Precipita	ation: I	Unknown						
Restrictions to Visibility: None															
Type of Pro	Type of Precipitation: None														
Accident	Accident Information														
Aircraft Damage: Minor Aircraft Fire: None Aircraft Explosion None															
Classificati	ion: U.S. Registered/l	J.S. Soil													
- Injury Su	mmary Matrix	Fatal	Serious	Minor		None	TOTAL					<u> </u>			
First Pi	ilot					1	1								
Second	d Pilot					1	1								
Studen	nt Pilot				\top	İ									
Flight I	nstructor					Ì									
Check	Pilot														
Flight E	Engineer														
Cabin /	Attendants		1		3	10	14								
Other C	Crew					1	1								
Passer	ngers		1		12	67	80								
- TOTAL /	ABOARD -		2		15	80	97								
Other 0	Ground	0	0		0		0								
- GRANE	O TOTAL -	0	2		15	80	97								
				•	•										

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: MIA94FA169

Occurrence Date: 06/29/1994

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

JEFFREY L. KENNEDY

Additional Persons Participating in This Accident/Incident Investigation:

JOEL NELSON AMERICAN AIRLINES FT. WORTH, TX 75261

JOE MANN FAA WASHINGTON, DC 20592

KENNETH J KORSHIN ALLIED PILOTS ASSOCIATION MIAMI, FL 33159

TOM MELODY DOUGLAS AIRCRAFT COMPANY LON BEACH, CA 90846