Tailstrike on landing, Boeing 757-24APF, December 25, 1994

Micro-summary: This Boeing 757 experienced a tail strike on landing.

Event Date: 1994-11-25 at 0549 CST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved. www.fss.aero

National Transportation Safety Board NTSB ID: FTW95LA055 Aircraft Registration Number: N413UP FACTUAL REPORT Occurrence Date: 11/25/1994 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 0549 **TULSA** OK 74115 CST Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft **BOEING** 757-24APF Airplane

Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 25, 1994, at 0549 central standard time, a Boeing 757-24APF, N413UP, was substantially damaged during landing at the Tulsa International Airport, in Tulsa, Oklahoma. The airplane, owned and operated by United Parcel Service, Inc., (UPS) as flight 732 and flown by two airline transport rated pilots, was on a 14 CFR Part 121 cargo flight. An IFR flight plan was in effect and visual meteorological conditions prevailed. Neither of the two crewmembers, the sole occupants, were injured.

Air Medical Transport Flight: No

During interviews conducted by the operator's flight standards division, the captain admitted to performing non-standard approaches previously, and he liked to "experiment with dynamic braking;" however, "he was not deliberately trying aerodynamic braking on this landing." Other crew members who had flown with the captain stated that "he often experimented and that he had a tendency toward non-compliance with standard operating procedures outlined in the UPS manuals."

The aircraft was equipped with a Fairchild model F1000 digital flight data recorder. The recorder was removed from the aircraft by the company and transported to Louisville, Kentucky, for read out and analysis. The recorder provided the following information: the approach was stable down to 50 feet, the approach speed was 130 knots (Vref +4), the airspeed was decreased to 118 knots (Vref minus 8 knots), the aircraft floated down the runway for approximately 8 seconds. The recorder also indicated that pitch attitude was increasing as the airspeed dissipated. The pitch attitude at touchdown was 7.3 degrees and reached 10.9 degrees in the next 5 seconds. A review of the UPS manuals determined that the approach did not comply with the published procedures for this aircraft.

Boeing Aircraft Company data, published to the users, states that the tail strike will occur at approximately 10.5 degrees pitch up attitude with gear struts compressed.

According to the operator, the airplane experienced a tail strike during landing which caused substantial structural damage. An inspection revealed damage to the belly skin, stringers, drain mast, and aft bulkhead.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW95LA055

Occurrence Date: 11/25/1994

AVIATION			Occurrence Type: Accident										
Landing Facility/Approach In	formation												
Airport Name Airpo				Airpo	ort Elevation	Runway Used Ru			Runway Length		Runway Wid	dth	
TULSA INTERNATIONAL TU			TUL		677 Ft. MSL	. 18	SL 10000)		200		
Runway Surface Type: Concrete													
Runway Surface Condition: Dry													
Type Instrument Approach: Visua	l												
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer BOEING				el/Series -24APF					Serial 2385	Number 3			
Airworthiness Certificate(s): Trans	sport								_				
Landing Gear Type: Retractable	- Tricycle												
Homebuilt Aircraft? No	Number of Seats: 6	Certifi	Certified Max Gross Wt.			250000	250000 LBS Numbe		er of Engines: 2				
			Engine M P&W	Engine Manufacturer: Model/Series: 2040							Rated Powe 40000 LB		
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time Sinc			nce Last Insp	ce Last Inspection Ai			e Total Tim	е		
Continuous Airworthiness			11/1994	11/1994 3 Hours					ours		8830 H	lours	
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? No	nstalled? No ELT Operated?				EL.	T Aided i	in Locating Ad	ccident S	ite?				
Owner/Operator Information													
Registered Aircraft Owner			Street	Street Address 1400 NORTH HURSTBOURNE PKWY									
UNITED PARCEL SERVICE II	NC		City							State	1 '		
			LOUISVILLE KY 40223 Street Address								3		
Operator of Aircraft			Same as Reg'd Aircraft Owner										
Same as Reg'd Aircraft Owner			City					State	Zip C	ode			
Operator Does Business As:						0	perator Desig	nator Co	de: IP)	ΚA	•		
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s)	: Flag Carrier/Dom	nestic											
Operating Certificate:				Or	perator Certifi	cate:							
Regulation Flight Conducted Unde	r: Part 121: Air Ca	arrier		•									
Type of Flight Operation Conducted	: Non-scheduled:	; Dome	estic; Carg	jo									
]	FACT	UAL REP	ORT - A	AVIATION						Page	e 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW95LA055

Occurrence Date: 11/25/1994

AVIATI	Occurrence Type: Accident									
First Pilot Information										
Name City								State	Date of Birth	Age
On File On I								On File	On File	48
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot							Certi	ificate Nun	nber: On File	
Certificate(s): Airlin	t; Flight Inst	ructor			·					
Airplane Rating(s): Multi-engine Land; Single-engine Land										
Rotorcraft/Glider/LTA: None										
Instrument Rating(s): Airplane										
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane										
Type Rating/Endorsement fo	r Accident/In	cident Aircra	ft? Yes		С	urrent Bienr	ial Flight Re	eview?		
Medical Cert.: Class 1 Medical Cert. Status: Valid Medicalw/ waivers/l							Date of Las	st Medical	Exam: 11/1994	
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Instru Actual	ment Simulated	Rotorcraf	t Glider	Lighter Than Air
Total Time	9000	1500	1500	7500	4500	900	100)		
Pilot In Command(PIC)	6000	1500	900	5900	3000	800	50)		
Instructor	1000		900	100	100	100	-			
Last 90 Days	200	200		200	170	20	4	ļ <u> </u>		
Last 30 Days Last 24 Hours	70 3	70 3		70 3	60 3					
Seatbelt Used? Yes	<u> </u>	Ider Harness	Used? Ves	3		logy Perforr	ned?	<u> </u>	Second Pilot? Ye	76
Coalbon Coca. 100	Toriou		0300: 163		Toxioo	nogy i onon			2000114 1101. 16	
Flight Plan/Itinerary										
Type of Flight Plan Filed: IFF	 R									
Departure Point					State	Airp	Airport Identifier		arture Time	Time Zone
LOUISVILLE						SDI	SDF		0	СЅТ
Destination						Airp	ort Identifier			
Same as Accident/Incident Location										
Type of Clearance: IFR										
Type of Airspace: Class E	≣									
Weather Information										
Source of Briefing: Company										
Method of Briefing:										
	FACTUAL REPORT - AVIATION Page 3									

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW95LA055

Occurrence Date: 11/25/1994

Occurrence Type: Accident

	c1 1 BO.												
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevatio	n	WOF Distance From Accident Site				Direction From Accident Site			
TUL	0554	CST		659 Ft. I	MSL	0 NM					0 Deg. Mag.		
Sky/Lowest Cloud Condition: Unknown				0 F					Condition of Light: Night/Dark				
Lowest Ceiling: Overcast				3900 Ft. AGL			ility:	10	SM	Altimeter: 30.00		"Hg	
Temperature: 9 °C Dew Point:				6 °C	Wind Direction: 200 Density Altitude:							Ft.	
Wind Speed: 5 Gusts:				Weather Condtions at Accident Site: Visual Conditions									
Visibility (F	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensit	y of Preci	pitation:	Unknown				
Restriction	s to Visibility: None	·											
Type of Pro	ecipitation: None												
Accident	Information												
Aircraft Damage: Substantial			Aire	Aircraft Fire: None					Aircraft Exp	losio	n None		
Classificati	on: Unknown												
- Injury Su	mmary Matrix	Fatal	Fatal Serious Mino			None	ne TOTAL						
First Pi	lot					1		1					
Second	d Pilot					1		1					
Studen	t Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	ngineer												
Cabin A	Attendants												
Other C	Crew												
Passen	igers												
- TOTAL A	ABOARD -					2		2					
Other 0	Ground	0	C		0			0					
- GRANE	TOTAL -	0	C		0	2		2					

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: FTW95LA055

Occurrence Date: 11/25/1994

Occurrence Type: Accident

	Information	

Investigator-In-Charge (IIC)

MATTHEW ELLIS,

Additional Persons Participating in This Accident/Incident Investigation:

LLOYD R COOK FAA FSDO OKLAHOMA CITY, OK 73108