# Tail stand collapse, Douglas 8-71F, November 30, 1994

Micro-summary: This Douglas 8-71F was damaged when the tail stand collapsed, causing a cargo pallet to hit a ground crew member.

Event Date: 1994-11-30 at 0535 CST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

## **Cautions:**

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

# National Transportation Safety Board FACTUAL REPORT AYIATION

NTSB ID: CHI95LA049

Aircraft Registration Number: N826BX

Occurrence Date: 11/30/1994

Most Critical Injury: Serious

Occurrence Type: Accident

Investigated By: NTSB

Location/Time

Airport Proximity: On Airport	Distance From	m Landing Facility:		Direction From	m Airport:
CHICAGO	IL	60666	0535	CST	
Nearest City/Place	State	Zip Code	Local Time	Time Zone	

Aircraft Information Summary

7 or are 1		
Aircraft Manufacturer	Model/Series	Type of Aircraft
DOUGLAS	DC-8-71F	Airplane

Sightseeing Flight: No

## Air Medical Transport Flight: No

### Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 30, 1994, about 0535 central standard time, Burlington Express flight 814, a Douglas DC-8-71F, N826BX, operated by Air Transport International, sustained minor damage when the tail stand collapsed at the O'Hare International Airport, Chicago, Illinois.

A ground crew member, who was unloading the airplane, reported serious injury. The three flight crew members, who had not deplaned, and three other ground crew members, also on board, reported no injuries. The 14 CFR Part 121 flight had landed at 0522 and visual meteorological conditions prevailed.

In a written statement, a representative of Burlington Express reported that the airplane landed in Chicago at 0522. He said a tail stand was installed and four cargo technicians boarded the plane and began downloading procedures.

The cargo locks in the front belly P1 position were removed and approximately 2,000 pounds of cargo were downloaded, leaving 2,100 pounds in the P1 position. The technicians were unlocking the P12 position and the airplane tail settled. The airplane sustained minor damage to the cargo door and an antenna.

The unlocked pallet from the P1 position rolled aft to the P11 position. Three of the technicians avoided the moving pallet. The fourth technician was trapped by the pallet and sustained serious injury to his foot.

The report stated that standard procedures for downloading the airplane were "possibly glazed over." Additionally, the scheduled turn around time for this flight was 45 minutes and "safety might be and has been compromised to make the turn".

A Federal Aviation Administration Inspector who responded to the accident reported that the airplane was unloaded improperly. The Burlington training manual specifies that the airplane should be unloaded from the rear of the airplane first.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI95LA049

Occurrence Date: 11/30/1994

AVIATION		Occu	rrence Type	e: Accident									
Landing Facility/Approach In	formation												
Airport Name			Airport ID:	Airport Eleva	ation	Run	way Used	Runwa	y Lengt	:h	Runw	vay Width	
O'HARE INTERNATIONAL			ORD	667 F	t. MSL	0							
Runway Surface Type:													
Runway Surface Condition:	Runway Surface Condition:												
Type Instrument Approach:													
VFR Approach/Landing:													
Aircraft Information													
Aircraft Manufacturer DOUGLAS				l/Series 3-71F					Serial 4599	Number 8			
Airworthiness Certificate(s): Transport													
Landing Gear Type: Retractable - Tricycle													
Homebuilt Aircraft? No	Number of Seats:	7	Certifie	ed Max Gross V	328000 LBS Number			er of Engines: 4					
Engine Type: Turbo Jet	Engine Manufacturer: Model/Series: CFM CFM56-2C-1						Rated Power: 22000 LBS						
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time Sine				nce Last Inspection Airfra				ne To	tal Time	
Continuous Airworthiness			11/1994				2 Hours				7	586 Hours	
- Emergency Locator Transmitter (	ELT) Information												
ELT Installed? Yes	ELT Operat	ed? No			EL	Aided i	n Locating Ac	cident S	ite?				
Owner/Operator Information													
Registered Aircraft Owner			Street	Address	STE	R HEIG	нтс						
AERO USA, INC.			83 WOOSTER HEIGHTS City							State	е	Zip Code	
			DANBURY									06810	
Operator of Aircraft			Street /	Address 3800 RO	DDNE	Y PARI	HAM ROAD						
AIR TRANSPORT INTERNAT	IONAL		City LITTLE ROCK						State		Zip Code 72212		
Operator Does Business As: BUR	Operator Designator Code: IXXA												
- Type of U.S. Certificate(s) Held:						•							
Air Carrier Operating Certificate(s)	: Flag Carrier/Don	nestic											
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 121: Air Carrier													
Type of Flight Operation Conducted	: Non-scheduled	; Dome	estic; Carg	0									
FACTUAL REPORT - AVIATION Page 2													

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: CHI95LA049

Occurrence Date: 11/30/1994

	AVIATI	QN	Occurrence Type: Accident												
First Pilot	t Information														
Name					T	City				Sta	ate	Date of Birth	Age		
On File						On File	ile			On	File	On File	53		
Sex: M	Seat Occupied	: Left	Prir	ncipal Profes	sion: Civilia	ın Pilot	ot Certificate Number: On File								
Certificate(	s): Airlir	ne Transpor	t; Commerc	ial											
Airplane Ra	ating(s): Mult	i-engine Lar	nd												
Rotorcraft/Glider/LTA: None															
Instrument Rating(s): Airplane															
Instructor Rating(s): None															
Type Rating/Endorsement for Accident/Incident Aircraft? Yes  Current Biennial Flight Review?															
Medical Ce	ert.: Class 1	Medica	al Cert. Status	: Valid Me	dicalw/ wa	aivers/lir	n.		Date of	Last M	ledical E	Exam: 06/1994			
		l													
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Instrument Actual Sim		ed	Rotorcraft	Glider	Lighter Than Air		
Total Time		18600	5600												
Pilot In Cor	mmand(PIC)	16000	5600												
Instructor															
Last 90 Da	ys														
Last 30 Da															
Last 24 Ho															
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes		1	Toxicology Performed? No Second Pilot? Yes						es		
Elight Dla	ın/Itinerary														
	ght Plan Filed: <b>[F</b>	 R													
Departure F						T	State	Air	port Ident	ifier	Depa	Time Zone			
										0000					
Destination	1						State	Air	Airport Identifier						
Local Flig	jht														
Type of Cle	earance: IFR														
Type of Air	space: Class	В													
Weather	Information														
Source of	Briefing:														
Method of	Briefing:														
	<u> </u>			E A CIETTA	DEDOD	A 7 77 1	TION						Day 6		
				FACTUAL	KEPORT	- AVIA	HON						Page 3		

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI95LA049

Occurrence Date: 11/30/1994

Occurrence Type: Accident

	FTYBON				. , , , ,	71001001									
Weather Information															
WOF ID	Observation Time	Time Zone	WOF	F Elevation	n	WOF D	WOF Distance From Accident Site Direction From A						n Accident Site		
ORD	0150	CST		667 Ft.	MSL				0 NM	0 Deg. Mag.					
Sky/Lowes	st Cloud Condition: Clear	-				0 Ft. /	AGL	Condition o	Condition of Light: Dawn						
Lowest Ce	eiling: None		0 Ft. <i>F</i>	AGL	Visib	Visibility: 10 SM A			Altii	ltimeter: 30.00 "Hg					
Temperatu	ure: -4 °C [	-7 °C	Wind	Direction:	Direction: 240 Density Altitude: 700 F										
Wind Spee	ed: 10	Gusts:		Weather Conditions at Accident Site: Visual Conditions											
Visibility (F	RVR): 0 Ft.	Visibility	/ (RVV)	0	SM	Intensit	y of Precip	oitation:	Unknown						
Restriction	Restrictions to Visibility: None														
Type of Precipitation: None															
Accident	Information														
Aircraft Da	mage: Minor		Air	craft Fire	: None	)			Aircraft Exp	losio	n None				
Classificati	ion: U.S. Registered/U.	S. Soil													
- Injury Su	mmary Matrix	Fatal	Serious	Minor None			TOTAL				_				
First Pi	ilot					1		1							
Second	d Pilot					1		1							
Studer	nt Pilot														
Flight I	nstructor														
Check	Pilot														
Flight E	Engineer			1		1		1							
Cabin /	Attendants														
Other (	Crew		,	1		3		4							
Passer	ngers			$\top$				7							
- TOTAL /		1		6		7									
Other (	Ground		0	0			0								
- GRANI	O TOTAL -	0		1	0										
-GRAND TOTAL-   U  1  U  6  /															

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: CHI95LA049

Occurrence Date: 11/30/1994

Occurrence Type: Accident

Investigator-In-Charge (IIC)

WESLEY M. ROBBINS,

Additional Persons Participating in This Accident/Incident Investigation:

LANCE R JACOBSEN FAA, 9950 W. LAWRENCE AVE SCHILLER PARK, IL 60176