## Birdstrike causing engine damage on a Boeing 737-300 at Portland, November 2, 1995

Micro-summary: Birdstrike on takeoff causes significant damage to an engine on this Boeing 737-3B7.

Event Date: 1995-11-02 at 1828 EST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

## **Cautions:**

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).

2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!

3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.

4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved. www.fss.aero

TRANSP National Transportation Safety Board		NTSB ID: NYC96IA022 Aircraft Registration Number: N373US							
			ce Date: 11/02	2/1995	Most Critical Injury: None				
ÁNIATIOŇ									
VETYBOA		Occurrent	ce Type: Incide	ent	Investigated By:	: NIS	В		
Location/Time	1			I					
Nearest City/Place	State			Time Zone					
PORTLAND	ME	04	4102	1828	EST				
Airport Proximity: On Airport         Distance From Landing Facility:         Direction From Airport:									
Aircraft Information Summary									
Aircraft Manufacturer     Model/Series     Type of Aircraft						Type of Aircraft			
BOEING			737-3B7				Airplane		
Sightseeing Flight: No		А	ir Medical Tr	ansport Flight: No	)				
Narrative									
Jetport, Portland, Maine. Th Instrument meteorological cond was operated on an Instrument F The CAPTAIN'S REPORT OF NO. At takeoff rotation we ex loud bang & excess declared & emergency procedu landing. According to the Power from RE-40, Aviation Engineerin The fuselage adjacent debris. An inspection o impacts or damageThere casingsFeathers and other fan, compressor, an damageFeather pieces[wer mollissima]. The weight of 6.4 pound) with the certification requirements for the engine must demonstrate to catch fire, burst or rel greater than the engine mount being shut downthe fracture the NTSB Materials labo	Bele narrative statement of facts, conditions and circumstances periment to the accident/incident: On November 2, 1995, at 1828 eastern standard time, a Boeing 737-3B7, N373US, operated by USAir as flight 1669, struck a bird in the number 2 engine, during takeoff from the Portland International Jetport, Portland, Maine. The occupants were not injured, and the airplane received minor damage. Instrument meteorological conditions prevailed, and the scheduled, domestic, passenger/cargo flight was operated on an Instrument Flight Rules (IFR) flight plan under 14 CFR 121. The CAPTAIN'S REPORT OF NON-STANDARD OR IRREGULAR OPERATION stated: At takeoff rotation we experienced an apparent bird strike in the #2 engine followed by a loud bang & excessive engine vibration. #2 engine was shut down, an emergency was declared & emergency procedures were followed ending with an uneventful single engine landing. According to the Powerplant Group Chairman Report, conducted by a Safety Board Investigator from RE-40, Aviation Engineering Services:The fuselage adjacent to the No. 2 engine did not have any apparent damage from engine debris. An inspection of the entire airplane did not show any indications of other bird impacts or damageFeather s and other organic debris identified to be bird remains were found in the fan, compressor, and combustor. There was no indication of any preexisting engine damageFeather pieces[were identified] as a female Common Eider (Somateria mollissima). The weight of the female Common Eider can range from 42 to 103 ounces (2.7 to 6.4 pound) with the average weight being 61 ounces (3.8 pounds)The airworthineess certification requirements for bird ingestion into a turbine engine case, generate loads greater than the engine mount attachment ultimate load limits, or lose the capability of being shut downthe fractured fan blades, and the superation for a server process the angent to the server superatis the output may not cause the engine to catch fire								

National Transportation Safety Boar	rd N	NTSB ID: NYC96IA022										
FACTUAL REPORT	Or	ccurren	ence Date: 11/02/1995									
<b>AVIATION</b>	0	ccurren	nce Type: Incident									
Landing Facility/Approach Inform	nation											
Airport Name	Airp	irport ID: Airport Elevation Runway Used Runway Leng						ay Lengtł	n Ru	nway Width		
PORTLAND INT'L JETPORT	PW	/M	74 Ft	74 Ft. MSL 11 6800				15	0			
Runway Surface Type: Asphalt												
Runway Surface Condition: Wet												
Type Instrument Approach: NONE												
VFR Approach/Landing: Precautionary Landing												
Aircraft Information												
Aircraft Manufacturer BOEING			Model/ 737-3						Serial I 22952	Number 2		
Airworthiness Certificate(s): Transport												
Landing Gear Type: Retractable - Tricycle												
Homebuilt Aircraft? No Nun	mber of Seats: 128		Certifie	d Max Gross W	/t.		135500	LBS	Numbe	r of Engine	es: 2	
Engine Type: Turbo Fan									ted Power: 2300 HP			
- Aircraft Inspection Information	- Aircraft Inspection Information											
Type of Last Inspection	Type of Last Inspection         Date of Last Inspection         Time Since Last Inspection         Airframe Total Time								otal Time			
Continuous Airworthiness								Ho	ours		Hours	
- Emergency Locator Transmitter (ELT)	Information											
ELT Installed? No	ELT Operated?				ELT A	ided in	n Locating Ac	cident S	Site?			
Owner/Operator Information												
Registered Aircraft Owner			Street A	ddress 2345 CR	YSTAL	DRI	VE					
USAIR			City							State	Zip Code	
		$\rightarrow$	Street A	ARLING	TON					VA	22227	
Operator of Aircraft			01100171		Reg'd	Aircra	aft Owner					
Same as Reg'd Aircraft Owner			City							State	Zip Code	
Operator Does Business As:						Op	perator Desig	nator Co	ode: US	AA		
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s): Flag	g Carrier/Domesti	.ic										
Operating Certificate:				Operator 0	Certificate	e:						
Regulation Flight Conducted Under: Pa	art 121: Air Carrie	er										
Type of Flight Operation Conducted: Sc	cheduled; Domes	tic; Pa	ssenger	r/Cargo								
FACTUAL REPORT - AVIATION Page 2												

Natior	ational Transportation Safety Board NTSB ID: NYC96IA022													
	ACTUAL RI		-	Occurrer	Occurrence Date: 11/02/1995									
l 1	AVIATI	~ ~			Occurrence Type: Incident									
		Part		Occurren	ice Type. III	ciuerii								
First Pilot Information       City       State       Date of Birth       Age														
										Age				
On File						On Fi	le				On File	Or	n File	43
Sex: M	Sex: M         Seat Occupied: Left         Principal Profession: Civilian Pilot         Certificate Number: On File													
Certificate(s): Airline Transport														
Airplane Rating(s): Multi-engine Land; Single-engine Land; Single-engine Sea														
Rotorcraft/	Glider/LTA: None	e												
Instrument	t Rating(s): Airpl	ane												
Instructor Rating(s): None														
Type Ratir	ng/Endorsement fo	or Accident/Ir	ncident Airc	raft? Yes			С	Current E	Biennial Fli	ght R	eview?			
Medical Co	ert.: Class 1	Medica	al Cert. Stat	tus: Valid Me	edicalno w	/aivers/	lim.		Date	of La	st Medica	l Exan	n: 05/1995	
- Flight Tir	me Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Ni	ght	Actual	Instrument Sim	ulated	Rotorcra	ıft	Glider	Lighter Than Air
Total Time	e	13140	271						800					
	ommand(PIC)					_					_			
Instructor						_					_			
Last 90 Da			210	)		_								
Last 30 Da	-													
	Ised? Yes	Shou	ı Ider Harne:	ss Used? Yes	<u> </u>		Toxico	loav Pe	erformed?	No		Secor	nd Pilot? Ye	۱ ۹
					, 								10	
Elight Pl	an/Itinerary													
	ight Plan Filed: IF	R												
Departure	<u> </u>						State	<u> </u>	Airport Ide	ntifie	r Dei	arture	Time	Time Zone
	Accident/Incide	nt Location					Olaid		PWM	, nuno	182			EST
Destinatio	n						Ctoto		Airport Ide	ntifia				
	Destination     State     Airport Identifier       PHILADELPHIA     PA     PHL													
Type of Cl	Type of Clearance: IFR													
Type of Ai	rspace: Class	с												
Weather	<sup>-</sup> Information													
Source of	Briefing: Compa	any												
Method of	Briefing													
	Dionity.													
				FACTUA	L REPORT	- AVL	ATIO	Ν						Page 3

Nationa	al Transportation Safety	Board	NTSB ID: NYC96IA022									
	ACTUAL REPOR		Occurren	ce Date:	11/02/1	995		1				
	AVIATION FTYBON		Occurren	Occurrence Type: Incident								
Weather	Information			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
WOF ID	Observation Time	Time Zone	WOF Elevat	DF Elevation WOF Distance From Accident Site Direction From Accid								
PWM	1856	EST	74 Ft	74 Ft. MSL 0 NM								
Sky/Lowest Cloud Condition: Unknown     0 Ft. AGL     Condition of Light: Night/Dark												
Lowest Ce	iling: Broken		300 Ft.	AGL	Visibi	ility:	1.75	SM	Alti	meter:	29.00	"Hg
Temperatu	ıre: 10 °C	Dew Point:	10 °C	Wind	Direction:	350			De	nsity Altitude:		Ft.
Wind Spee	ed: 9	Gusts:		Weath	ner Condt	ions at Accio	lent Si	<sup>ite:</sup> Instrum	ent C	Conditions		
Visibility (R	RVR): 0 Ft	. Visibility (	RVV) 0	SM	Intensity	y of Precipita	ation:	Light				
Restriction	s to Visibility: Fog	1										
Type of Pre	ecipitation: Rain											
.,												
Accident	Information											
Aircraft Dar	mage: Minor		Aircraft Fi	e: None				Aircraft Exp	olosio	n None		
Classificati	on: U.S. Registered/L	J.S. Soil	<b>I</b>									
- Injury Su	mmary Matrix	Fatal	Serious Min	or	None	TOTAL						
First Pi					1	1						
Second	d Pilot				1	1						
Studen	t Pilot											
Flight li	nstructor											
Check	Pilot											
Flight E	Engineer											
Cabin A	Attendants				4	4						
Other C	Crew											
Passen	igers				56	56						
- TOTAL A	ABOARD -				62	62						
Other G	Ground	0	0	0		0						
- GRANE	D TOTAL -	0	0	0	62	62						
			FACTUAI	REPO	RT - AV	IATION					F	Page 4

National Transportation Safety Board	NTSB ID: NYC96IA022	
FACTUAL REPORT	Occurrence Date: 11/02/1995	
AVIATION ETYBON	Occurrence Type: Incident	
dministrative Information	·	
vestigator-In-Charge (IIC)		
ROBERT L. HANCOCK		
dditional Persons Participating in This Accident	t/Incident Investigation:	
RAYMOND CLOUTIER FAA FSDO		
PORTLAND, ME		
JAMES HOOKEY		
AS-40 (POWERPLANTS) WASHINGTON, DC		
JOE EPPERSON		
RE-30 MATERIALS LAB DIV		
WASHINGTON, DC		
GEORGE SNYDER USAIR		
PITTSBURGH, PA		