## Uncontained engine failure, Boeing 747-251B, January 5, 1996

**Micro-summary:** This Boeing 747-251B experienced an uncontained engine failure of the #4 engine during climb.

Event Date: 1996-01-05 at 1230 PST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

## **Cautions:**

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).

2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. *Your company's flight operations manual is the final authority as to the safe operation of your aircraft*!

3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.

4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved. www.fss.aero

National Transportation Safety Board		NTSB I	D: LAX96IA087	7	Aircraft Registration Number: N628US				
FACTUAL REPORT		Occurr	ence Date: 01/05	5/1996	Most Critical Injury: None				
AVIATION	Occurre	ence Type: Incid	ent	Investigated By: NTSB					
Location/Time									
Nearest City/Place         State         Zip Code         Local Time         Time Zone									
LOS ANGELES	CA		90045	1230	PST				
Airport Proximity: Off Airport/Airstrip       Distance From Landing Facility:       Direction From Airport:									
Aircraft Information Summary									
Aircraft Manufacturer			Model/Series	S			Type of Aircraft		
Boeing			747-251B				Airplane		
Sightseeing Flight: No			Air Medical Tr	ansport Flight: No	C				
Narrative									
Narrative Brefarative statement of facts, conditions and circumstances pertinent to the accident/incident: On January 5, 1996, about 1200 hours Pacific standard time, a Boeing 747-251B, N628US, sustained an uncontained failure of the number 2 engine turbine section during the en route climb phase of flight near Los Angeles, California. The aircraft was operated by Northwest Airlines, Inc., as their flight number 1, a regularly scheduled non-stop international passenger flight from Los Angeles to Narita Airport, Tokyo, Japan. Visual meteorological conditions prevailed at the time and an IFR flight plan was filed for the flight. The aircraft sustained minor damage to the numbers 1 and 2 engine cowls, and the fan stage of the number 1. engine. None of the 366 passengers and 19 crew onboard were injured. The flight originated from Los Angeles International Airport about 1145 on the morning of the accident. The captain reported that while climbing through 11,500 feet ms1 the airplane began to shake and the low rotor (N1) rpm on the number 2 engine surged to 90 percent, then dropped to 40 percent, as the exhaust gas temperature rose to the redline limit. The glareshield red fire warning light illuminated and the fire bell sounde; however, the red light in the number 2 fire handle did not illuminate. The second officer noticed that the number 2 engine nacelle temperature indication also reached its upper limit. The engine was secured in accordance with the "Engine fire, Severe Damage, or Separation Checklist" and the fire bolt accordance with the "Engine cowl turbine area at the 9 o'clock position. No evidence of fire outside the engine case was observed. Minor dents were noted on the number 1 engine cowl, pylon, and the underside of the left wing. Several fan blades from the number 1 engine cowl, pylon, and the underside of the left wing. Several fan blades from the number 1 engine cowl, pylon, and the underside of the left wing. Several fan blades from the number 1 engine cowl, pylon, and the									
The fractured oil pressure tube was removed from the engine and submitted to the Safety Board's Materials Laboratory for metallurgical analysis. The complete metallurgical report is appended to this document. According to the report, fatigue striations were found indicative of multiple fatigue crack planes from multiple origins along the inside diameter of the tube, with propagation									
FACTUAL REPORT - AVIATION Page 1									

National Transportation Safety Board	NTSB ID: LAX96IA087	
FACEUAL REPORT	Occurrence Date: 01/05/1996	
	Occurrence Type: Incident	

## Narrative (Continued)

mainly through the thickness of the tube wall. Spiral scratches and crazed cracking were found on the tube's inside wall. The fatigue fracture planes observed followed the scratches and crazed cracking lines in the central fatigue initiation region.

Northwest Airlines and Pratt & Whitney maintenance/overhaul documents relating to the overhaul and cleaning of the number 4 bearing internal pressure tube assembly were examined. Cautionary notes state that wire brushes or reamers are not to be used for internal cleaning of the tubes. The referenced documents are appended to this report and list the approved cleaning methods.

National Transportation Safety Board	1	NTSB ID:	GB ID: LAX96IA087									
FACTUAL REPORT	Occurren	Iccurrence Date: 01/05/1996										
AVIATION		Occurren	се Туре:									
Landing Facility/Approach Information												
Airport Name	Airp	ort ID:	Airport Eleva	tion	Run	way Used	Runwa	ay Length	n Ru	nway Width		
			Ft	. MSL	0							
Runway Surface Type:												
Runway Surface Condition:												
Type Instrument Approach:												
VFR Approach/Landing: None												
Aircraft Information									i			
Aircraft Manufacturer			Model/	Series					Serial N	Number		
Airworthingen Cartificate(a): Transport			/4/-2	.516					22308	0		
Airwortniness Certificate(s). Transport												
Landing Gear Type: Retractable - Tric	ycle											
Homebuilt Aircraft? No Num	Iomebuilt Aircraft? No Number of Seats: 373 Certified Max Gross Wt. 833000 LBS Number of E								r of Engine	es: 4		
Engine Type: Turbo Fan	Er P	Engine Manufacturer:Model/Series:P&WJT9D-7Q							Rated Power: 53000 LBS			
- Aircraft Inspection Information												
Type of Last Inspection		Da	Date of Last Inspection Time Since Last Inspection							Airframe 1	Total Time	
Continuous Airworthiness			Hours						ours		Hours	
- Emergency Locator Transmitter (ELT)	Information											
ELT Installed? Yes	ELT Operated? ELT Aided in Locating Accident Site?											
Owner/Operator Information												
Registered Aircraft Owner			Street A	ddress 5101 NC	RTHW	/EST	DRIVE					
NORTHWEST AIRLINES, INC.		-	City State								Zip Code	
			SI PAUL MN 55111									
Operator of Aircraft			Slieel A	Same as	Reg'd	I Aircra	aft Owner					
Same as Reg'd Aircraft Owner	-	City State Zip								Zip Code		
Operator Does Business As: Operator Designator Code: NWAA									•			
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s): Flag	Carrier/Domes	stic										
Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under: Part 121: Air Carrier												
Type of Flight Operation Conducted: Scheduled; International; Passenger Only												
FACTUAL REPORT - AVIATION Page 2												

Nation	TRANS	Safety Board	1	NTSB ID	NTSB ID: LAX96IA087									
F	ACTUAL RI	EPORT	-	Occurren	Occurrence Date: 01/05/1996									
· ·	AVIATI	ωN		Occurren										
First Pilot Information														
Name City								y State Date of Birth						Age
On File					On File On File On									59
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot Certificate Number: On File														
Certificate(s): Airline Transport; Flight Engineer														
Airplane Rating(s): Multi-engine Land; Single-engine Land														
Rotorcraft/	Glider/LTA: None	e		-										
Instrument	t Rating(s): Airpl	lane												
Instructor Rating(s): None														
Type Ratin	ng/Endorsement fo	or Accident/Ir	ncident Airo	craft? Yes			C	Current E	Biennial Fl	ight R	eview?			
Medical Ce	ert.: Class 1	Medica	al Cert. Sta	atus: Valid Me	dicalw/ w	aivers/l	im.		Date	e of La	st Medica	Exan	n: 11/1995	
- Flight Tir	me Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Airplane Night Single Engine Mult-Engine			Actual	Instrument I Simulated		Rotorcra	ft	Glider	Lighter Than Air
Total Time	9	12000												
Pilot In Co	mmand(PIC)										_			
Instructor						_					_			
Last 90 Da	ays										_			
Last 30 Da	ays										_			
Last 24 Ho	burs						T				<u> </u>	0		
Seatbelt U	sed? Yes	Shou	Ider Harne	ess Used? Yes	6		IOXICO	Diogy Pe	errormed?	NO		Seco	na Pliot? Ye	S
Flight Pla	an/Itinerary													
Type of Fli	ight Plan Filed: IF	R											I	
Departure	Point						State Air		Airport Id	irport Identifier		Departure Time		Time Zone
Same as	Accident/Incide	ent Location					LA		LAX	AX		1145		PST
Destination	n						State Airport Ide			entifie	r		<b>I</b>	
токуо							OF RJAA							
Type of Clearance: IFR														
Type of Airspace: Class A														
Weather Information														
Source of Briefing: Company														
Method of	Briefing:													
	-			FACTUA	LREPORT	- AVI/	ATIO	N						Page 3

National Transportation Safety Board			NTS	NTSB ID: LAX96IA087								
F	Occ	urrence D	Date: (	01/05/19	996		1					
	Occ	urrence T	vpe: I	ncident			1					
Weather	Information				71-0-1							
WOF ID Observation Time Time Zone WOF Elevation WOF Distance From Accid									dent Site		Direction From	Accident Site
-												
	0000			0 Ft. MS	SL				0 NM			0 Deg. Mag.
Sky/Lowes	st Cloud Condition: Cle	ar				_	0 Ft. AG	L	Condition of	of Lig	nt: Day	
Lowest Ce	illing: None			0 Ft. AG	3L	Visibi	lity:	100	SM	Alti	meter:	"Hg
Temperatu	ıre: °C	Dew Point:		°C V	Wind D	irection:				De	nsity Altitude:	Ft.
Wind Spee	ed:	Gusts:		V	Veathe	er Condti	ons at Accic	lent Si	ite: Visual (	Cond	itions	
Visibility (F	RVR): 0 Ft	. Visibility	(RVV)	0 s	SM	Intensity	of Precipita	ation: I	Unknown			
Restriction	is to Visibility: None	I										
	-											
Type of Pr	ecipitation: None											
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,												
Accident	Information											
Aircraft Da	mage: Minor		Aircr	aft Fire: N	None				Aircraft Exp	olosio	n None	
Classificati	ion: U.S. Registered/l	J.S. Soil										
- Injury Su	mmary Matrix	Fatal	Serious	Minor	N	lone	TOTAL					
First Pi	ilot					1	1					
Second	d Pilot					2	2					
Studen	t Pilot											
Flight I	nstructor											
Check	Pilot											
Flight E	Engineer					2	2					
Cabin /	Attendants					14	14					
Other 0	Crew											
Passer	ngers					366	366					
- TOTAL A	ABOARD -					385	385					
Other 0	Ground	0	0		0		0					
- GRANE	D TOTAL -	0	0		0	385	385					
			FACT	FUAL RI	EPOR	T - AV	IATION					Page 4

National Transportation Safety Board	NTSB ID: LAX96IA087	
FACTUAL REPORT	Occurrence Date: 01/05/1996	
AVIATION	Occurrence Type: Incident	
Administrative Information		
Investigator-In-Charge (IIC)		
JEFF RICH		
Additional Persons Participating in This Accident/Incid	ent Investigation:	
DON SKUNBERG FAA WP-FSDO-LAX LOS ANGELES, CA 90048		