
Stuck elevator, Airbus A320, November 24, 1996

Micro-summary: This Airbus A320-211's rudder stuck at zero deflection at 50' AGL on landing.

Event Date: 1996-11-24 at 1450 EST


Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC
All rights reserved.
www.fss.aero

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI97IA034		Aircraft Registration Number: N310NW	
		Occurrence Date: 11/24/1996		Most Critical Injury: None	
		Occurrence Type: Incident		Investigated By: NTSB	
Location/Time					
Nearest City/Place ROMULUS	State MI	Zip Code 48174	Local Time 1450	Time Zone EST	
Airport Proximity: On Airport		Distance From Landing Facility: 1		Direction From Airport: 215	
Aircraft Information Summary					
Aircraft Manufacturer Airbus Industrie		Model/Series A-320-211		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
<p>HISTORY OF FLIGHT</p> <p>On November 24, 1996, at 1450 eastern standard time (est), an Airbus A320-211, N310NW, operated as Northwest Airlines flight 211, experienced a rudder system malfunction approximately 50 feet above ground level (agl) while transitioning from approach to landing on runway 3L at Detroit Metropolitan Airport, Romulus, Michigan. The airplane was subsequently landed with the rudder stuck at zero deflection. While taxiing to the gate, the rudder system returned to normal. Instrument meteorological conditions prevailed at the time of the incident. The flight was being conducted as regular scheduled domestic air carrier service under 14 CFR Part 121. An IFR flight plan was on file. There were no reported injuries to the 6 crew and 141 passengers who deplaned normally at the gate. The flight originated at Fort Lauderdale, Florida, at 1130 est.</p> <p>In his written statement, the captain said that he "was at the controls, conducting a manually flown (autopilot off) ILS approach." He said that the weather conditions "were approximately 1,100 feet overcast with very light icing in the clouds. There was a right-quartering tailwind on final which subsided to a very light crosswind over the runway threshold. Due to this light crosswind, a slight application of rudder/wing low compensation was required for the flare and landing." When the captain attempted to use the rudder, he found that the rudder pedals "were locked in the neutral position." The captain used slight banking to keep the airplane on runway centerline through the touchdown. After touchdown, the captain used differential braking to stay on runway centerline. On reaching a ground speed of approximately 80 knots, the captain used nosewheel steering for directional control.</p> <p>During the landing roll, the captain asked the first officer to come on the rudder pedals with him. The first officer stated that he did not apply any force, but did notice that "the rudder pedals seemed stiff or possibly locked."</p> <p>After exiting the runway, the captain performed several autopilot disconnects using the autopilot disengage button on the control stick. "This had no effect other than to verify that there was truly no autopilot involvement." The captain then made several attempts to move the rudder pedals. "After about 15 seconds of this, the rudders became free and moved normally."</p> <p>AIRCRAFT INFORMATION</p> <p>Northwest Airlines Maintenance conducted a post-incident inspection at Romulus, Michigan, on November 25, 1996. First, a test of the autopilot disengagement system was conducted. The test revealed no anomalies in the autopilot system. Northwest Airlines Maintenance then examined all of the rudder system control components from the cockpit to the rudder control surfaces. No indications of mechanical anomalies were found. No signs of water or ice were found through the rudder cable inspection. The rudder attach points were cold soaked with dry ice. No binding was</p>					
<div style="display: flex; justify-content: space-between;"> FACTUAL REPORT - AVIATION Page 1 </div>					

National Transportation Safety Board

FACTUAL REPORT**AVIATION**

NTSB ID: CHI97IA034

Occurrence Date: 11/24/1996

Occurrence Type: Incident

Narrative (Continued)

noted. The rudder autopilot artificial feel solenoid was removed, replaced and retained for further examination.

METEOROLOGICAL INFORMATION

The National Weather Service Weather Observation Facility at Detroit Metropolitan Airport's 1455 est observation was a 400 foot overcast ceiling, 3 miles visibility with drizzle and mist. The temperature was 33 degrees Fahrenheit. The dew point was 30 degrees Fahrenheit. The surface winds were 040 degrees magnetic at 7 knots.

TESTS AND RESEARCH

The flight data recorder was removed on November 26, 1996, and read out on December 6, 1996. A review of the flight data recorder readout showed that the autopilot was disengaged at the time of the incident. The data showed some movement in the crew's rudder pedal positions during the landing. The data showed little to no movement of the rudder surfaces.


A review of all airworthiness directives and service bulletins with respect to the A-320 rudder system revealed an Airbus Industrie service bulletin dated March 21, 1992 entitled "Flight Controls-Rudder-Increase Radial Play of Lever Bearing in the Artificial Feel and Trim Unit." The service bulletin addressed conditions where the A-320 rudder artificial feel and trim unit did not disengage from the autopilot mode to normal pedal operating forces during approach and landing. "Investigations have shown that the radial play of the autopilot mode engagement/disengagement lever bearing together with low temperature could cause an increased operating force. In this case, the back driving force is not able to rotate the lever to get the autopilot mode disengaged." The service bulletin introduced a new modified lever with a larger radial play of the bearing to eliminate this problem. The A-320-211, N310NW, did not have this modification at the time of the incident.


The rudder autopilot artificial feel unit was tested in the laboratories of Aerospatiale in Toulouse, France on January 27, 1997. A representative from the Bureau Enquetes-Accidents (BEA) was present to oversee the testing. The examination revealed that the "radial play of the autopilot mode engagement/ disengagement lever was not sufficient. This introduced a higher friction in the bearing of the lever, resulting in an increased operating force. In this case, the back driving force is not able to rotate the lever to get the autopilot mode disengaged. This results in increased pedal forces to move the rudder."


ADDITIONAL INFORMATION

Parties to the investigation were the Federal Aviation Administration, Northwest Airlines, Airbus Industrie of North America, and the Air Line Pilot's Association.

The airplane was released and put back into service on November 25, 1996. The flight data recorder and rudder autopilot artificial feel solenoid were released and returned to Northwest Airlines.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI97IA034				
		Occurrence Date: 11/24/1996				
		Occurrence Type: Incident				
Landing Facility/Approach Information						
Airport Name DETROIT METROPOLITAN		Airport ID: DTW	Airport Elevation 640 Ft. MSL	Runway Used 3L	Runway Length 12001	Runway Width 200
Runway Surface Type: Concrete						
Runway Surface Condition: Wet						
Type Instrument Approach: ILS-complete						
VFR Approach/Landing: Full Stop						
Aircraft Information						
Aircraft Manufacturer Airbus Industrie		Model/Series A-320-211		Serial Number 121		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 156		Certified Max Gross Wt. 167000 LBS	Number of Engines: 2	
Engine Type: Turbo Fan		Engine Manufacturer: Cfm		Model/Series: CFM-56	Rated Power: 25000 LBS	
- Aircraft Inspection Information						
Type of Last Inspection Continuous Airworthiness		Date of Last Inspection 05/1996		Time Since Last Inspection 2972 Hours	Airframe Total Time 20190 Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed?		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner FIRST NATIONAL BANK OF BOSTON		Street Address 2 INTERNATIONAL PLACE				
		City BOSTON		State MA	Zip Code 02110	
Operator of Aircraft NORTHWEST AIRLINES		Street Address 5101 NORTHWEST DRIVE				
		City ST. PAUL		State NM	Zip Code 55111	
Operator Does Business As:				Operator Designator Code: NWAA		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						
FACTUAL REPORT - AVIATION						

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI97IA034																																																																																		
		Occurrence Date: 11/24/1996																																																																																		
		Occurrence Type: Incident																																																																																		
First Pilot Information																																																																																				
Name		City		State	Date of Birth																																																																															
On File		On File		On File	Age																																																																															
					45																																																																															
Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot		Certificate Number: On File																																																																																
Certificate(s): Airline Transport; Flight Engineer																																																																																				
Airplane Rating(s): Multi-engine Land; Single-engine Land																																																																																				
Rotorcraft/Glider/LTA: None																																																																																				
Instrument Rating(s): Airplane																																																																																				
Instructor Rating(s): None																																																																																				
Type Rating/Endorsement for Accident/Incident Aircraft? Yes				Current Biennial Flight Review?																																																																																
Medical Cert.: Class 1		Medical Cert. Status: Valid Medical--no waivers/lim.		Date of Last Medical Exam: 08/1996																																																																																
<table border="1"> <tr> <th rowspan="2">- Flight Time Matrix</th> <th rowspan="2">All A/C</th> <th rowspan="2">This Make and Model</th> <th rowspan="2">Airplane Single Engine</th> <th rowspan="2">Airplane Multi-Engine</th> <th rowspan="2">Night</th> <th colspan="2">Instrument</th> <th rowspan="2">Rotorcraft</th> <th rowspan="2">Glider</th> <th rowspan="2">Lighter Than Air</th> </tr> <tr> <th>Actual</th> <th>Simulated</th> </tr> <tr> <td>Total Time</td> <td>5242</td> <td>2883</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Pilot In Command(PIC)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Instructor</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 90 Days</td> <td>221</td> <td>221</td> <td></td> <td>221</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 30 Days</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 24 Hours</td> <td>8</td> <td>8</td> <td></td> <td>8</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>						- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Actual	Simulated	Total Time	5242	2883									Pilot In Command(PIC)											Instructor											Last 90 Days	221	221		221							Last 30 Days											Last 24 Hours	8	8		8						
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night							Instrument					Rotorcraft	Glider	Lighter Than Air																																																																	
						Actual	Simulated																																																																													
Total Time	5242	2883																																																																																		
Pilot In Command(PIC)																																																																																				
Instructor																																																																																				
Last 90 Days	221	221		221																																																																																
Last 30 Days																																																																																				
Last 24 Hours	8	8		8																																																																																
Seatbelt Used? Yes		Shoulder Harness Used? Yes		Toxicology Performed? No																																																																																
				Second Pilot? Yes																																																																																
Flight Plan/Itinerary																																																																																				
Type of Flight Plan Filed: IFR																																																																																				
Departure Point		State	Airport Identifier	Departure Time	Time Zone																																																																															
FORT LAUDERDALE		FL	FLL	1130	EST																																																																															
Destination		State	Airport Identifier																																																																																	
Same as Accident/Incident Location			DTW																																																																																	
Type of Clearance: IFR																																																																																				
Type of Airspace: Class B																																																																																				
Weather Information																																																																																				
Source of Briefing: Company																																																																																				
Method of Briefing:																																																																																				


 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI97IA034	
		Occurrence Date: 11/24/1996	
		Occurrence Type: Incident	

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
DTW	1455	EST	640 Ft. MSL	1 NM	215 Deg. Mag.
Sky/Lowest Cloud Condition: Unknown			0 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: Overcast		400 Ft. AGL	Visibility: 3 SM	Altimeter: 30.00	"Hg
Temperature: 1 °C	Dew Point: -1 °C	Wind Direction: 40		Density Altitude: 750	Ft.
Wind Speed: 7	Gusts:	Weather Conditions at Accident Site: Instrument Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: Freezing Rain					

Accident Information					
Aircraft Damage: None		Aircraft Fire: None		Aircraft Explosion: None	
Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				4	4
Other Crew					
Passengers				141	141
- TOTAL ABOARD -				147	147
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	147	147

--

FACTUAL REPORT - AVIATION	Page 4
---------------------------	--------

 National Transportation Safety Board FACTUAL REPORT AVIATION	NTSB ID: CHI97IA034	
	Occurrence Date: 11/24/1996	
	Occurrence Type: Incident	
Administrative Information		
Investigator-In-Charge (IIC) DAVID C. BOWLING		
Additional Persons Participating in This Accident/Incident Investigation: MARK LUND FAA CMO-6020 28TH AVE. SOUTH MINNEAPOLIS, MN 55450 TIMOTHY J LOGAN NORTHWEST-5101 NORTHWEST DR. MINNEAPOLIS, MN 55111 ROBERT F ARRON, JR. ALPA-5101 NORTHWEST DR. MINNEAPOLIS, MN 55111 ALAIN DERON AIRBUS-7500 AIRLINE DR MINNEAPOLIS, MN 55450		
FACTUAL REPORT - AVIATION Page 5		