
Main landing gear failure on landing, Boeing 727-247, July 6, 1997

Micro-summary: This Boeing 727-247 encountered a main landing gear failure while landing, resulting in an evacuation.


Event Date: 1997-07-06 at 1650 MDT


Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: FTW97FA255		Aircraft Registration Number: N2809W	
		Occurrence Date: 07/06/1997		Most Critical Injury: Minor	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place ALBUQUERQUE		State NM	Zip Code 87106	Local Time 1650	Time Zone MDT
Airport Proximity: On Airport		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer Boeing		Model/Series 727-247		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
<p>HISTORY OF FLIGHT</p> <p>On July 6, 1997, at 1650 mountain daylight time, a Boeing 727-247 airplane, N2809W, was substantially damaged when the right main landing gear collapsed during landing roll on runway 21 at Albuquerque International Airport, Albuquerque, New Mexico. The 3 airline transport rated pilots, 3 flight attendants, and 147 passengers were not injured; however, 3 passengers sustained minor injuries during the emergency evacuation from the airplane. The airplane was being operated by Delta Airlines Inc. as flight 1470 under Title 14 CFR Part 121. Visual meteorological conditions prevailed for the scheduled domestic passenger flight which originated at Dallas/Fort Worth International Airport 1 hour and 17 minutes before the accident. An IFR flight plan had been filed for the flight.</p> <p>According to the captain, this was the first leg of the rotation for the flight crew and he was the flying pilot. He characterized the flight as "normal", but did observe some distant thunderstorms as they approached Albuquerque (not in the vicinity of the destination airport). The captain reported that they were originally assigned runway 8 for landing, but air traffic control (ATC) changed that to runway 21 approximately 25 miles from their destination. The first officer stated that ATC cleared them for a visual approach and a "normal stabilized approach was flown." He further described the landing as "average for a 727, nothing remarkable." The captain reported that the wind was "right down the runway for the landing."</p> <p>The captain stated that after touchdown, the spoilers were deployed and reverse thrust selected. He said "as the airplane slowed to approximately 70 KIAS, I moved the thrust levers out of reverse and applied light to moderate wheel brakes." The first officer reported hearing a "loud bang," which was his first indication of a problem. He said that the airplane began "listing heavily to the right and drifting to the right." As the airplane came to a stop on the runway, all three pilots noticed that the right unsafe gear light was illuminated and they concluded that the right main landing gear had collapsed.</p> <p>The captain stated that "he was sure the wing was on the ground, and there was approximately 16,000 pounds of fuel onboard." He ordered the first officer to radio for airport rescue and fire fighting (ARFF) personnel to assist them and the second Officer to read the evacuation checklist. The cockpit door was opened and the forward flight attendant was directed to begin evacuation of the passengers. The 1R, 2R, and 2L emergency slides were deployed and the evacuation began. The forward Flight Attendant reported that "the passengers were almost too calm; they appeared to have no sense of urgency." He reported that he yelled out instructions to the passengers at first and then the captain suggested using the megaphone. According to the flight attendant, using the megaphone "seemed to reduce the stress in my voice which in turn seemed to reduce the overall stress, and the megaphone seemed to work better than the public address system."</p>					
FACTUAL REPORT - AVIATION					
Page 1					

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: FTW97FA255
	Occurrence Date: 07/06/1997
	Occurrence Type: Accident

Narrative (Continued)

The two flight attendants in the rear of the airplane were notified of the evacuation by interphone. They both reported having "some difficulty" opening their respective emergency doors and motivating the passengers to evacuate expeditiously. They both used voice commands to communicate with passengers.

INJURIES TO PERSONS

After the evacuation was completed, three women requested medical assistance. Two of the women received treatment by paramedics on scene; a third woman was taken to a local hospital for further examination and treatment.

DAMAGE TO AIRPLANE

Examination of the airplane revealed that right main landing gear forward trunnion bearing support fitting had failed at the 9 o'clock and 3 o'clock position of the bearing lug. The following right wing components were damaged: the main landing gear, the lower spar cap of the wing spar tip, the aft portion of the wing tip, all leading edge slats and their tracks, the aileron control cable had been broken, all the flaps, an 18"x8" hole in the upper wing skin, and the spoiler beam.

AIRCRAFT INFORMATION

Boeing Commercial Airplane Group manufactured 1,832 B-727s from February 1964 to September 1984. The accident airplane was built in 1972 and had accumulated 74,734 hours of flight time (50,711 cycles) when the right main landing gear (MLG) failed. The MLG were last removed for overhaul on April 8, 1988 and had accumulated 26,496 hours of flight time (18,188 cycles) since overhaul. The Boeing Commercial Airplane Group recommended that the MLG be overhauled every 12,000 cycles (this can be adjusted based on fleet experience in conjunction with regulatory approval). Delta Airline's maintenance was scheduling MLG overhaul for not more than 120 months or 30,000 flight hours, whichever came first (Delta averages 1.3 hours per cycle). The forward trunnion support fitting, a component of the MLG, has no manufacturer's specified life limit. That is, there is no requirement when the part must be taken out of service.

On May 24, 1989, a Delta Airlines Boeing 727-247, N296WA, had its left MLG collapse during push-back due to the failure of the MLG forward trunnion bearing support fitting. The airplane had 25,391 flight hours on its airframe and a total of 17,187 flight cycles at the time of the event. A third MLG forward trunnion bearing support fitting failure occurred on October 1, 1972 on a United Airlines, Inc. Boeing 727 during landing roll at San Francisco International Airport. After the May 24, 1989 failure, Delta Airlines ultrasonically inspected its entire fleet of Boeing 727s; 3 additional airplanes were found with cracks in their forward trunnion bearing support fitting. No cracks or corrosion were identified on the accident airplane.

On March 8, 1990, Boeing issued Service Bulletin number 727-57-0179 to inspect the forward trunnion bearing support fitting for stress corrosion cracking on all 727 airplanes using ultrasonic inspection (which could detect cracks and corrosion as small as .050 inches in depth). If no corrosion or cracks were found, the operator was to ultrasonically inspect their airplanes again at a maximum time between inspections of six months or 1,500 flight cycles, whichever occurred first. They were to continue this inspection cycle until the part was repaired or the preventative modification was done.

On January 13, 1991, a Service Bulletin revision was issued by Boeing to add an additional recommendation for corrosion protection and to expand the use of sealant to coat the trunnion fitting lug bore during its reassembly onto the MLG of the airplane. On April 30, 1992, Boeing issued revision 2, of Service Bulletin 727-57-0179 (see attached document). The Boeing Service Bulletin called for an ultrasonic inspection of the part after 12,000 flight cycles with a maximum time between inspections of 1500 cycles or 6 months. Inspections were to continue until the part

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: FTW97FA255

Occurrence Date: 07/06/1997

Occurrence Type: Accident

Narrative (Continued)

was repaired or the fitting was replaced. Inspections could cease if the new (revised in April 1992) repair was accomplished or the fitting replaced.

Delta Airline's maintenance had planned for the removal of the accident airplane's MLG for inspection and overhaul approximately 274 cycles after the accident. The procedure would have been required by Delta maintenance 3,504 hours after the accident. The removal of the MLG is the only time that the MLG forward trunnion bearing support fitting can be visually inspected for corrosion or cracking.

Delta Air Lines maintenance records indicate that during May 1993, the right MLG forward trunnion bearing support fitting of the accident airplane was ultrasonically inspected. The airplane flew 11,723 hours (7,634 cycles) until the accident in Albuquerque on July 6, 1997. Delta Airline's maintenance states that its current trunnion bracket inspection program follows the requirements of Service Bulletin number 727-57-0179, Rev. 2.


TESTS AND RESEARCH


The NTSB Materials Laboratory examined the airplane's right main landing gear forward trunnion bearing support fitting. According to the Materials Laboratory Report, the failure of the fitting was the result of stress corrosion cracking. The stress corrosion cracking was precipitated by fatigue cracking that had radially propagated from three corrosion pitting locations on the bore surface of the fitting in the area adjacent to its forward face (see attached report).

X-ray energy dispersive spectroscopy (EDS) analysis of corrosion deposits at the fracture origin area revealed the presence of sulfur, chlorine, and oxygen. Various other low atomic number elements and the elements normally associated with 4330M steel specified for the fitting were also detected in these areas. EDS analysis in the area of the fracture containing no evidence of corrosion product generated spectra consistent with chemical composition of the specified material.

ADDITIONAL DATA

The airplane was released to a Delta Airlines representative on July 10, 1997; the forward trunnion bearing support fitting and spherical bearing from the right main landing gear were released to Delta Airlines on February 10, 1998.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: FTW97FA255				
		Occurrence Date: 07/06/1997				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name ALBUQUERQUE INTERNATIONAL		Airport ID: ABQ	Airport Elevation 5352 Ft. MSL	Runway Used 17	Runway Length 10000	Runway Width 150
Runway Surface Type: Asphalt						
Runway Surface Condition: Dry						
Type Instrument Approach: Visual						
VFR Approach/Landing: Full Stop						
Aircraft Information						
Aircraft Manufacturer Boeing		Model/Series 727-247		Serial Number 20581		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 157	Certified Max Gross Wt. 184200 LBS		Number of Engines: 3	
Engine Type: Turbo Fan		Engine Manufacturer: P&W		Model/Series: JT8D-15A	Rated Power: 15500 LBS	
- Aircraft Inspection Information						
Type of Last Inspection Continuous Airworthiness		Date of Last Inspection 06/1997	Time Since Last Inspection 119 Hours		Airframe Total Time 9198 Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed? No		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner DELTA AIR LINES, INC.		Street Address HARTSFIELD INTL. AIRPORT				
		City ATLANTA		State GA	Zip Code 30320	
Operator of Aircraft Same as Reg'd Aircraft Owner		Street Address Same as Reg'd Aircraft Owner				
		City		State	Zip Code	
Operator Does Business As: DELTA AIR LINES, INC.				Operator Designator Code: DALA		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						
FACTUAL REPORT - AVIATION						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: FTW97FA255
	Occurrence Date: 07/06/1997
	Occurrence Type: Accident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 54
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport; Commercial

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): None

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review?
---	---------------------------------

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 06/1997
------------------------	--	------------------------------------

- Flight Time Matrix

	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	15325	4984								
Pilot In Command(PIC)										
Instructor										
Last 90 Days	164	164								
Last 30 Days										
Last 24 Hours	2	2		2						

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point DFW AIRPORT	State TX	Airport Identifier DFW	Departure Time 1547	Time Zone MDT
--------------------------------	-------------	---------------------------	------------------------	------------------

Destination Same as Accident/Incident Location	State	Airport Identifier ABQ	
---	-------	---------------------------	--


Type of Clearance: IFR

Type of Airspace: Class C

Weather Information

Source of Briefing:
Company

Method of Briefing:


 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: FTW97FA255
	Occurrence Date: 07/06/1997
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
ABQ	1709	MDT	5352 Ft. MSL	2 NM	40 Deg. Mag.
Sky/Lowest Cloud Condition: Scattered			8000 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: Broken		12000 Ft. AGL		Visibility: 10 SM	Altimeter: 30.00 "Hg
Temperature: 30 °C	Dew Point: 4 °C	Wind Direction: 210		Density Altitude: Ft.	
Wind Speed: 11	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: Substantial	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer				1	1
Cabin Attendants				3	3
Other Crew					
Passengers			3	147	150
- TOTAL ABOARD -			3	153	156
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	3	153	156

--	--

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: FTW97FA255
	Occurrence Date: 07/06/1997
	Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

JAMES F. STRUHSAKER

Additional Persons Participating in This Accident/Incident Investigation:

GARY R GOMES
FAA FSDO
ALBUQUERQUE, NM 87106

JOHN HAMILTON
BOEINGCOMMERCIAL AIRPLANE GRP
SEATTLE, WA 98124

RALPH E HICKS, JR.
DELTA AIRLINES
ATLANTA, GA 30320

JIM D SHAW
ALPA
HERDON, VA 22070