## Galley lift injury, Boeing 747-422, June 9, 1999

Micro-summary: This Boeing 747-422 experienced incorrect operation of a galley lift, seriously injuring a flight attendant.

Event Date: 1999-06-09 at 0245 GMT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

### Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

#### National Transportation Safety Board NTSB ID: LAX99LA212 Aircraft Registration Number: N198UA FACTUAL REPORT Occurrence Date: 06/09/1999 Most Critical Injury: Serious Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone PACIFIC OCEAN PO 0245 **GMT** Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip

Boeing 747-422

Type of Aircraft

Airplane

Sightseeing Flight: No

Aircraft Manufacturer

Aircraft Information Summary

Air Medical Transport Flight: No

#### Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On June 9, 1999, about 0245 hours coordinated universal time, a Boeing 747-422, N198UA, operating as United Airlines Flight 890, experienced a serious cabin attendant injury while en route from Singapore to Narita, Japan. The flight over international waters had departed Singapore at 2341 on June 8, 1999, destined for Narita. The flight was operated by United Airlines, Inc., of Chicago, Illinois, as a scheduled international passenger flight under 14 CFR Part 121 of the Federal Aviation Regulations. Neither the airline transport pilot captain and first officer, the remaining 17 cabin attendants or 306 passengers were injured.

Model/Series

At 0245, the captain contacted dispatch and reported a diversion to Hong Kong due to an accident in the galley involving a flight attendant. According to a United Airlines report, the flight attendant was injured in the main deck galley while using the lift to move carts to the upper deck.

The flight attendant was in the process of placing a cart in the lift when it began to move, having been called from the upper deck. The upward movement of the lift caused the cart to roll out of the lift, striking and pinning the flight attendant against the galley wall. The lift continued to raise, catching the edge of the cart, and lifting it off the floor, trapping the flight attendant between the other end of the cart and the galley counter opposite the lift. As the cart was raised off the floor, the flight attendant was lifted off her feet and her body was pushed on top of the galley counter. The cart continued to rise, pinning the flight attendant's face between the cart and the bins above the galley counter.

An inspection of the galley lift at Hong Kong revealed a piece of cardboard had been inserted into the interlock safety switch, disabling it, and by doing so, the galley lift can be operated without closing the galley lift door.

As a result of other similar upper deck cart accidents/incidents Boeing has issued a Service Bulletin 747-25-3187 to modify the control panel to allow only the person working on the cart lift to send it.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX99LA212

Occurrence Date: 06/09/1999

AVIATION			Occurrence Type: Accident										
Landing Facility/Approach Information													
Airport Name			Airpor	rt ID:	Airport Eleva	t Elevation Runway Used R			Runwa	Runway Length		Runv	vay Width
					Ft.	MSL	0						
Runway Surface Type:													
Runway Surface Condition:													
Type Instrument Approach:													
VFR Approach/Landing:													
Aircraft Information													
Aircraft Manufacturer											ll Number		
Boeing				747-4	22					2871	6		
Airworthiness Certificate(s): Norm	al												
Landing Gear Type: Retractable	- Tricycle												
Homebuilt Aircraft? No	lomebuilt Aircraft? No Number of Seats: 391						Certified Max Gross Wt.					gines	: 4
					Engine Manufacturer: Model/Series: P&W P&W4056								d Power: 00 LBS
- Aircraft Inspection Information													
Type of Last Inspection Da					Date of Last Inspection Time Sind					nce Last Inspection			tal Time
Continuous Airworthiness			08/1	08/1998					4002 Hours				439 Hours
- Emergency Locator Transmitter (	ELT) Information												
ELT Installed?		ELT Aided in Locating Accident Site?											
Owner/Operator Information													
Registered Aircraft Owner	S	Street Address P.O. BOX 99100											
UNITED AIRLINES INC.					City							e	Zip Code
					CHICAGO Street Address								60666
Operator of Aircraft			51	treet A		ST A	LONQL	JIN ROAD					
UNITED AIRLINES					City							ie	Zip Code
					ELK GROVE TOWNS IL  Operator Designator Code: UALA								60007
Operator Does Business As: - Type of U.S. Certificate(s) Held:							0	perator Design	nator Co	ide. UA	LA		
Air Carrier Operating Certificate(s)		nestic											
All Garrier Operating Gertineate(5)	, riag camen zon												
Operating Certificate:					Operator C	Certific	ate:						
Regulation Flight Conducted Unde	r: Part 121: Air Ca	arrier											
Type of Flight Operation Conducted	: Scheduled; Inte	ernatio	nal; Pa	assen	ger Only								
		FACT	UAL I	REPO	RT - AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX99LA212

Occurrence Date: 06/09/1999

AVIATION	Occurrence Type: Accident												
First Pilot Information													
Name	City					State	е [	Date of Birth	Age				
On File	On File	е				On F	File	On File	58				
Sex: M Seat Occupied: Left	n Pilot		Certificate Number: On File										
Certificate(s): Airline Transport; Flight Engineer													
Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA: None													
Instrument Rating(s): Airplane													
Instructor Rating(s): None													
Type Rating/Endorsement for Accident/Incident Aircraft? Yes  Current Biennial Flight Review?													
Medical Cert.: Class 1	Medical	Cert. Status	: Valid Med	dicalno wa	aivers/li	im.		Da	ate of La	st Med	dical Ex	am: 04/1999	
- Flight Time Matrix	Flight Time Matrix  All A/C  This Make and Model		Airplane Single Engine	Airplane Mult-Engine	Night		Actual	Instrument Simulat		Rotorcraft		Glider	Lighter Than Air
Total Time 19127 603		603											
Pilot In Command(PIC)						_		$\perp$					
Instructor					-			_		$\perp$			
Last 90 Days		117											
Last 30 Days 77							_		+				
Last 24 Hours Seatbelt Used? Yes	Chaula	8	Haada Vaa		1.	Tovios	logy De	rformo	43				
Seatbelt Used? Yes	Should	der Harness	Usea? Yes			TOXICC	ology Pe	enormed	11		Se	CONG PIIOL? YE	S
Flight Plan/Itinerary													
Type of Flight Plan Filed: IFR													
Departure Point					T	State	Т	Airport Identifier			Departure Time		Time Zone
SINGAPORE						OF		SIN			0725		
Destination						State		Airport	Identifie	r			
NARITA		OF		NRT									
Type of Clearance: IFR													
Type of Airspace: Class A													
Weather Information													
Source of Briefing: Company													
Method of Briefing:													
FACTUAL REPORT - AVIATION Page 3													

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: LAX99LA212

Occurrence Date: 06/09/1999

TYBOR				Occurrence Type: Accident									
Weather Information													
WOF ID	Observation Time	Time Zone	WOF	Elevation	on	WOF Di	istance From Accident Site				Direction From Accident Site		
	0000			0 Ft.	MSL				0 NM			0 Deg. Mag.	
Sky/Lowes	t Cloud Condition: Unk		0				L Condition of L			ight: Day			
Lowest Ce		0 Ft. AGL			lity:	0	SM	Altimeter:		"Hg			
Temperatu		°C Wind Direction:						Density Altitude: Ft.					
Wind Spee		Weather Conditions at Accident Site: Visual Conditions							itions				
Visibility (F	y (RVV)	0 SM Intensity of Precipitation: Unknown											
Restriction	s to Visibility: None	-											
Type of Pro	ecipitation: None												
Accident	Accident Information												
Aircraft Da	Airo	Aircraft Fire: None					Aircraft Exp	losio	n None				
Classificati	on: U.S. Registered/L	J.S. Soil											
- Injury Summary Matrix Fatal			Serious	ous Minor		None	TOTAL						
First Pi	lot					1	1						
Second	d Pilot					1	1						
Studen	t Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	ngineer												
Cabin A	Attendants		1			17	18						
Other C	Crew												
Passer	gers					306	306						
- TOTAL A	ABOARD -		1			325	326						
Other 0	Ground	0	0		0		0						
- GRANE	TOTAL -	0	1		0	325	326						
					•								

National Transportation Safety Board

# FACTŲAL REPORT AVIATION

NTSB ID: LAX99LA212

Occurrence Date: 06/09/1999

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

GEORGE E. PETTERSON

Additional Persons Participating in This Accident/Incident Investigation:

MIKE WHITE SFO-IFO BURLINGAME, CA 94010

JEFF PLANTZ UNITED AIRLINES INC CHICAGO, IL 60666