
Main landing gear collapse during taxi, Douglas DC-9-32, September 22, 2002

Micro-summary: The right main landing gear of this Douglas DC-9-32 collapsed during taxi.

Event Date: 2002-09-22 at 1852 CDT


Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC
All rights reserved.
www.fss.aero

		NTSB ID: CHI02FA289		Aircraft Registration Number: N941N	
		Occurrence Date: 09/22/2002		Most Critical Injury: None	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place Minneapolis		State MN	Zip Code 55450	Local Time 1852	Time Zone CDT
Airport Proximity: On Airport		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer McDonnell Douglas		Model/Series DC-9-32		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On September 22, 2002, at 1852 central daylight time, a McDonnell Douglas DC-9-32, N941N, owned and operated by Northwest Airlines as flight 1842, was substantially damaged when the right main landing gear collapsed during taxi at the Minneapolis-St. Paul International/Wold-Chamberlain Airport, Minneapolis, Minnesota. The 14 CFR Part 121 passenger flight was taxiing for takeoff and was bound for the Charlotte/Douglas International Airport, Charlotte, North Carolina. There were no injuries to the 81 passengers or 4 crewmembers.</p> <p>The airplane departed from gate D3 and was taxiing on taxiway A to runway 30L when the right main landing gear collapsed. The airplane came to rest on taxiway A abeam gate F10. The right main landing gear outer-cylinder was found fractured into three pieces about 19 inches from the upper end of the cylinder. The fracture surface was visually examined and a dark spot was observed on the forward side the fracture surface of the cylinder. The cylinder was then removed from the aircraft and shipped to the National Transportation Safety Board's Materials Laboratory in Washington, D.C., for further examination.</p> <p>The airplane, serial number 47450, was manufactured in 1969 and had accumulated 85,323 hours time in service, which included 74,121 landing cycles. The right main landing gear had accumulated a total of 105,099 landing cycles. The operator reported that the right main landing gear was last overhauled on April 22, 1995, and had accumulated 11,275 landing cycles in 18,446 hours time in service.</p> <p>Laboratory examination of the fracture surface revealed that the fracture originated from the dark spot that was previously observed. This dark spot was examined using various methods and was found to have several areas with differing fracture features. The first region, centered on the fracture origin, showed intergranular fracture features. The first region was surrounded by a thin band, region 2, that exhibited transgranular fracture features that resembled fatigue progression in steel materials. Region 2 was also surrounded by a third region that again exhibited intergranular fracture features. Another band, region 4, surrounded region 3 and exhibited fatigue progression features. Outside of these regions, the fracture faces exhibited features consistent with overstress fracture.</p> <p>A metallographic section of the upper surface of the fracture was made. The section was cut and polished perpendicular to the fracture face so that the polished surface intersected region 1. Multiple sulfide inclusions were found in the sectioned sample. Similarly, a section was made of the lower surface of the fracture, and a 0,012-inch long line of inclusions was found. This line of inclusions was oriented perpendicular to the fracture region and parallel to the outer surface of the cylinder. The inclusions were determined to be composed mainly of oxides of aluminum and calcium with others containing sulfides of iron and manganese.</p> <p>Scanning electron microscope examination of the metallographic samples determined that the material</p>					
FACTUAL REPORT - AVIATION					
Page 1					

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: CHI02FA289

Occurrence Date: 09/22/2002

Occurrence Type: Accident

Narrative (Continued)

was consistent with the material specified on engineering drawings for the part. Additionally, hardness testing indicated that the strength levels were also consistent with the engineering specification.

Additional testing was performed under the direction of the NTSB on samples from the landing gear of N941N and N8986E. N8986E is a McDonnell Douglas DC-9-31 that was damaged when its landing gear collapsed during landing at MSP (NTSB accident number CHI02FA148). The tests performed included dissolved hydrogen content, residual stress, tensile properties, notched tensile strength and sustained load tests. The results of the testing are summarized below.

Hydrogen content ranged from 1 to 5 ppm for both cylinders. Each cylinder was tested at three locations near the fracture.

Both cylinders had compressive stress layers at the outer surfaces consistent with shot peened surfaces. The residual stress profiles showed maximum compressive stresses of about 200 to 250 ksi transitioning to residual tensile stresses between 0.01 and 0.02 inch below the surface. Both cylinders were tested at two locations, one near the dark spot at the origin of the fracture and another remote from the dark spot. No significant differences were noted between locations.


Tensile tests of material from both cylinders met engineering drawing and specification requirements for tensile strength, yield strength, elongation and reduction in area.


Notched tensile strength was about 325,000 psi for both specimens. This property is not controlled by drawing or specification but is used in the sustained load tests.

Specimens from both cylinders passed 200 hour sustained load tests without failure.

Samples of both cylinders were tested for cleanliness by magnetic particle inspection. No significant inclusions were detected and both exceeded the requirements for cleanliness.

Parties to the investigation were the Federal Aviation Administration, Northwest Airlines, The Boeing Company, Air Line Pilots Association, and the Aircraft Mechanics Fraternal Association.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI02FA289				
		Occurrence Date: 09/22/2002				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name		Airport ID:	Airport Elevation	Runway Used	Runway Length	Runway Width
MINNEAPOLIS-ST PAUL INTL/WOLD-		MSP	841 Ft. MSL	NA		
Runway Surface Type:						
Runway Surface Condition:						
Type Instrument Approach:						
VFR Approach/Landing:						
Aircraft Information						
Aircraft Manufacturer		Model/Series		Serial Number		
McDonnell Douglas		DC-9-32		47450		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 85	Certified Max Gross Wt. 109800 LBS		Number of Engines: 2	
Engine Type:		Engine Manufacturer:		Model/Series:	Rated Power:	
Turbo Jet		Pratt & Whitney		JT8D-15	15500 LBS	
- Aircraft Inspection Information						
Type of Last Inspection		Date of Last Inspection	Time Since Last Inspection		Airframe Total Time	
AAIP		09/2002	105 Hours		62452 Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed? No		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner		Street Address				
		5101 Northwest Drive C7-8960				
NORTHWEST AIRLINES INC		City		State	Zip Code	
		St. Paul		MN	55111	
Operator of Aircraft		Street Address				
		Same as Reg'd Aircraft Owner				
Same as Reg'd Aircraft Owner		City		State	Zip Code	
Operator Does Business As:				Operator Designator Code: NWAA		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						
FACTUAL REPORT - AVIATION						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: CHI02FA289
	Occurrence Date: 09/22/2002
	Occurrence Type: Accident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 43
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): None

Instructor Rating(s): None

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review? 09/2002
---	---

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 06/2002
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	4221	2025								
Pilot In Command(PIC)		1815								
Instructor										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point Same as Accident/Incident Location	State	Airport Identifier MSP	Departure Time 1852	Time Zone CDT
---	-------	---------------------------	------------------------	------------------

Destination CHARLOTTE	State NC	Airport Identifier CLT	
--------------------------	-------------	---------------------------	--


Type of Clearance: Unknown

Type of Airspace: Unknown

Weather Information

Source of Briefing: No record of briefing


Method of Briefing: Unknown

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: CHI02FA289
	Occurrence Date: 09/22/2002
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
KMSP	1853	CDT	841 Ft. MSL	0 NM	0 Deg. Mag.
Sky/Lowest Cloud Condition: Few			6000 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: Broken		20000 Ft. AGL		Visibility: 10 SM	Altimeter: 30.10 "Hg
Temperature: 12 °C	Dew Point: 2 °C	Wind Direction: 300		Density Altitude: Ft.	
Wind Speed: 5	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): Ft.	Visibility (RVV) SM	Intensity of Precipitation:			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: Substantial	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				2	2
Other Crew					
Passengers				81	81
- TOTAL ABOARD -				85	85
Other Ground					
- GRAND TOTAL -				85	85

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: CHI02FA289
	Occurrence Date: 09/22/2002
	Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

John M. Brannen

Additional Persons Participating in This Accident/Incident Investigation:

James Freseman
FAA-Minneapolis, Minnesota - CMO
2901 Metro Drive, Suite 500
Bloomington, MN 55425

Patrick Schmitz
Air Safety Investigator
Northwest Airlines
Dept N7218, 5101 Northwest Drive
St Paul, MN 55111

James Wegener
Aircraft Mechanics Fraternal Association
7801 Metro Parkway
Bloomington, MN 55425

William B Etzold
Air Line Pilots Association
4570 Neal Ave N.
Stillwater, MN 55082

William Steelhammer
Sr. Flight Safety Investigator
Boeing Long Beach Division
3855 Lakewood Blvd.
Long Beach, CA 90846