

---

## Tire tread loss, damage, Boeing 737-436, G-DOCV

---

**Micro-summary:** This Boeing 737-436 experienced a loss of tire tread, resulting in significant gear well damage.

---

**Event Date:** 1996-06-10 at 1933 UTC

**Investigative Body:** Aircraft Accident Investigation Board (AAIB), United Kingdom

**Investigative Body's Web Site:** <http://www.aaib.dft.gov/uk/>

**Note:** Reprinted by kind permission of the AAIB.

---

### Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
  2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
  3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
  4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

# Boeing 737-436, G-DOCV

**AAIB Bulletin No: 1/97 Ref: EW/G96/06/13 Category: 1.1**

## INCIDENT

<b>Aircraft Type and Registration:</b>	Boeing 737-436, G-DOCV
<b>No &amp; Type of Engines:</b>	2 CFM56-3C1 turbofan engines
<b>Year of Manufacture:</b>	1992
<b>Date &amp; Time (UTC):</b>	10 June 1996 at 1933 hrs
<b>Location:</b>	London Heathrow Airport
<b>Type of Flight:</b>	Public Transport
<b>Persons on Board:</b>	Crew - 7 - Passengers - 88
<b>Injuries:</b>	Crew - None - Passengers - None
<b>Nature of Damage:</b>	Damage to the main landing gear door, hydraulic pipes and electrical cables and to a wing flap and spoiler
<b>Commander's Licence:</b>	Airline Transport Pilot's Licence
<b>Commander's Age:</b>	46 years
<b>Commander's Flying Experience:</b>	13,690 hours (of which 8,800 were on type) Last 90 days - 94 hours Last 28 days - 2 hours
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot and AAIB telephone inquiries

The aircraft was taking-off on Runway 27R at Heathrow Airport for a scheduled flight to Inverness. The wind was from 270°M at 5 kt, ambient temperature was 20°C and the runway surface was dry. The crew felt a slight shimmy on take-off rotation at 135 kt and ATC subsequently advised that tyre and metallic debris had been found on the runway.

The flight diverted to Glasgow Airport. On arrival a low pass was made in order for ground personnel to view the underside of the aircraft; this failed to positively identify the problem. The aircraft then made an uneventful landing at Glasgow. It was found that the right hand tyre of the right main landing gear was severely distressed, with the entire tread missing, together with substantial parts of the carcass outer plies. The landing gear door had been severely damaged and damage had also resulted to hydraulic pipelines and to an electrical cable conduit associated with the

right landing gear anti-skid system. The wing flap trailing edge and the under surface of the No 5 spoiler panel were also damaged.

Information from the operator suggested that the tyre tread had partially separated following damage inflicted by contact with a foreign object. A piece of metallic debris was found in the same area as the tyre debris; it was identified as a blocker door from a Rolls Royce RB211-524G or 524H engine but it was not possible to ascertain its origin. Examination of the tyre by the manufacturer found no signs of pre-failure defect and also indicated that the damage was most likely to have been caused by impact with a sharp object when the tyre had been rotating at high speed. It appeared that the flailing tread had caused the damage to the landing gear door, the hydraulic pipes and the electrical cables and that the damaged door had then detached under aerodynamic loading and struck the flap and the spoiler.