
Wheel separation on takeoff, Boeing 737-222, April 7, 1995

Micro-summary: This Boeing 737-222 lost a wheel on takeoff.


Event Date: 1995-04-07 at 1710 CDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: CHI95IA119		Aircraft Registration Number: N9090U	
		Occurrence Date: 04/07/1995		Most Critical Injury: None	
		Occurrence Type: Incident		Investigated By: NTSB	
Location/Time					
Nearest City/Place CHICAGO	State IL	Zip Code 60666	Local Time 1710	Time Zone CDT	
Airport Proximity: On Airport		Distance From Landing Facility: 0		Direction From Airport: 0	
Aircraft Information Summary					
Aircraft Manufacturer BOEING		Model/Series 737-222		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>HISTORY OF THE FLIGHT</p> <p>On April 8, 1995, at 1710 central daylight time(cdt), a Boeing 737-222, N9040U, aircraft number 9640, operated under 14 CFR Part 121 as United Airlines (UAL) flight #536 to Atlanta, Georgia, experienced a left outboard (#1 main) wheel separation on takeoff from runway 09L at Chicago O'Hare International Airport (ORD). The left inboard wheel was unaffected and remained installed. The airplane returned to ORD and landed on runway 32L without incident at 1846 cdt after circling to burn fuel. The 111 passengers and 5 crewmembers were uninjured, and deplaned via the stairs. The wheel damaged two fences and several rental cars in parking lots located on the airport.</p> <p>Detailed laboratory inspection revealed a failure of the outboard wheel bearing. Indications of grease migration outboard, out of the bearing cavity, was evident. The recovered bearing components exhibited mechanical deformation and heat distress. This damage precluded a definite determination of the initiating failure. The December 5, 1995, engineering report by the Timken Company on "The Investigation of Landing Gear Parts, Aircraft #9640" states that a likely cause of the bearing failure was inadequate lubrication.</p> <p>The Timken report was written at the request of the National Transportation Safety Board, and parties to the investigation were the NTSB, Timken, UAL, Allied Landing Systems (ALS), and Boeing Aircraft Company. All parties were present at the Timken facility during the physical inspection, and all have made comments which are incorporated in or appended to the Timken report.</p> <p>Boeing comments state "...no definitive cause was established, but the hardware condition was consistent with a failure stemming from inadequate lubrication."</p> <p>Twenty five of twenty seven rollers were recovered. No fragments of the two unrecovered rollers were apparent (Reference paragraph #3, page 6, under "General Discussion" of Timken report 12/5/95). The bearing cage was destroyed during the failure. Timken stated "there was no evidence for there having been one or more cracked rollers, and that the damage in the failed bearing was not consistent with such a condition."</p> <p>HISTORY OF THE FAILED BEARING</p> <p>A review of maintenance records on the wheel assembly indicated that the #1 main wheel had been installed on February 1, 1995, at 55,443 aircraft cycles. A brake change was performed on February 25, 1995, at 55,573 cycles. The wheel loss occurred at 55,792 cycles.</p> <p>This is a total of 219 cycles since the brake change, and 349 cycles since installation. It could not be determined if the bearing was repacked with grease during the brake change.</p>					
FACTUAL REPORT - AVIATION					

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: CHI95IA119

Occurrence Date: 04/07/1995

Occurrence Type: Incident

Narrative (Continued)

The outboard bearing cup exhibited date code "ZD" which indicates a manufacturing date of February 1993 (approximately 26 months). Timken (the bearing manufacturer) stated this age is not exceptional.

BEARING LIFE EXPECTANCY

Bearings are installed with wheel assemblies after buildup, and remain installed until the wheel is removed and disassembled. This normally occurs as a result of tire removal due to tread wear or tire damage. There is no high cycle limit placed on tires or wheel assemblies. Removals are "on condition" based on tire tread.

Timken stated that "...with rare exceptions, rolling contact fatigue is not a condition observed as a life limitation of aircraft wheel bearings."

Boeing indicated a worldwide 737-200 fleet average of 200 cycles between tire changes (which would require repacking or installation of a new bearing).

UAL provided a sample of 19 737-200 tire changes. The high life tire in the sample was removed at 326 landing cycles. The average (mean) tire life was 259 cycles, with a standard deviation of 39.9 cycles. The failed bearing remained installed to 349 cycles.

LUBRICATION PROCEDURES

At initial installation, the wheel assembly has a freshly grease packed new or re-used and inspected bearing. During a brake change, if the wheel assembly is reinstalled, the bearing may not be repacked if it visually appears to have grease.

UAL Maintenance Procedures for 737-200 Wheel and Tire Assembly - Removal / Installation, 32-41-01, paragraph 2. D (4), states "Install outer bearing (packed with GRE4500-8A)." The procedures for Main Gear Wheel Brake - Removal / Installation, 32-43-01, paragraph 7. J. states, "Install main gear wheel (Ref. 32-41-01/201)."

The Safety Board investigator asked UAL maintenance personnel to clarify these procedures. Line maintenance supervisors from UAL San Francisco Engineering stated that personnel may interpret this to mean that if the outer bearing was removed from the wheel, or a new one installed, that the bearing would be repacked with grease. If the wheel was removed as an assembly for a brake change, and then reinstalled as an assembly, the bearing would not necessarily be repacked.

Interviews with three FAA airworthiness inspectors, two of whom had B-737 experience, indicated that during a brake change where a wheel was removed and reinstalled, they would expect a mechanic to visually inspect the wheel. They stated that if grease was visually present, they would not expect a mechanic to repack the bearing.

TYPE OF LUBRICANT

UAL repair shop working documents specify Aeroshell-5 as an approved lubricant by Allied Landing Systems in CMM 32-40-01. Aeroshell-5 was confirmed by lab testing to be the grease in use.

Timken stated that they and ALS have recommended Aeroshell-22 as a superior grease for aircraft wheel applications, but that Aeroshell-5 has shown acceptable performance.

No discrepancy with the use of Aeroshell-5 was noted.

RETENTION OF LUBRICANT

National Transportation Safety Board

FACTUAL REPORT**AVIATION**

NTSB ID: CHI95IA119

Occurrence Date: 04/07/1995

Occurrence Type: Incident

Narrative (Continued)

UAL Maintenance Procedures for 737-200 Wheel and Tire Assembly - Removal / Installation, 32-41-01, paragraph 2. D (4), states "Outer seal (adjacent to axle nut) no longer required." This refers to a grease dam, part number 2602576, depicted on Allied Landing System drawing 2601571-1. This grease dam is designed to retain lubricant within the bearing cavity, and is optional as per ALS.


The failed wheel assembly exhibited radial streaks of grease which had migrated out of the bearing cavity.


Boeing stated that the majority of 737-200 airplanes in service worldwide operate without the optional grease dam installed.


AGE OF LUBRICANT


The UAL procedures in place specify for a brake change to refer to the wheel removal/installation procedures. These procedures refer to the installation of a packed bearing. Statements by various FAA inspectors, and UAL, indicate that if grease was visually present, a bearing may or may not actually be repacked with fresh grease by a mechanic on the line. The wheel may be reinstalled with the original grease. The failed wheel bearing had grease which was either 219, or 349 cycles old.

Allied Landing Systems and Timken indicate that after approximately 150 cycles, lubricant degradation begins to accelerate in aircraft wheel bearings.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI95IA119			
		Occurrence Date: 04/07/1995			
		Occurrence Type: Incident			
Landing Facility/Approach Information					
Airport Name	Airport ID:	Airport Elevation	Runway Used	Runway Length	Runway Width
O'HARE INT'L AIRPORT	ORD	650 Ft. MSL	9L	7967	150
Runway Surface Type: Asphalt					
Runway Surface Condition: Dry					
Type Instrument Approach: ILS-complete; Visual					
VFR Approach/Landing: Precautionary Landing; Straight-in					
Aircraft Information					
Aircraft Manufacturer		Model/Series		Serial Number	
BOEING		737-222		19078	
Airworthiness Certificate(s): Normal; Transport					
Landing Gear Type: Retractable - Tricycle					
Homebuilt Aircraft? No	Number of Seats: 117	Certified Max Gross Wt.	117000 LBS	Number of Engines: 2	
Engine Type:	Engine Manufacturer:	Model/Series:	Rated Power:		
Turbo Jet	P&W	JT8D-7B	14000 LBS		
- Aircraft Inspection Information					
Type of Last Inspection	Date of Last Inspection	Time Since Last Inspection	Airframe Total Time		
Continuous Airworthiness	11/1994	794 Hours	51274 Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed?	ELT Operated?	ELT Aided in Locating Accident Site?			
Owner/Operator Information					
Registered Aircraft Owner UNITED AIR LINES, INC.		Street Address O'HARE INTERNATIONAL AIRPORT			
		City CHICAGO	State IL	Zip Code 60666	
Operator of Aircraft Same as Reg'd Aircraft Owner		Street Address Same as Reg'd Aircraft Owner			
		City	State	Zip Code	
Operator Does Business As: UNITED AIR LINES			Operator Designator Code: UALA		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): Flag Carrier/Domestic					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Part 121: Air Carrier					
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only					
<div>FACTUAL REPORT - AVIATION</div> <div>Page 2</div>					

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI95IA119																																																																																		
		Occurrence Date: 04/07/1995																																																																																		
		Occurrence Type: Incident																																																																																		
First Pilot Information																																																																																				
Name On File		City On File		State On File	Date of Birth On File																																																																															
					Age 38																																																																															
Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot		Certificate Number: On File																																																																																
Certificate(s): Airline Transport; Flight Instructor																																																																																				
Airplane Rating(s): Multi-engine Land; Single-engine Land																																																																																				
Rotorcraft/Glider/LTA: None																																																																																				
Instrument Rating(s): Airplane																																																																																				
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine																																																																																				
Type Rating/Endorsement for Accident/Incident Aircraft? Yes				Current Biennial Flight Review?																																																																																
Medical Cert.: Class 1		Medical Cert. Status: Valid Medical--no waivers/lim.		Date of Last Medical Exam: 12/1994																																																																																
<table border="1"> <tr> <th rowspan="2">- Flight Time Matrix</th> <th rowspan="2">All A/C</th> <th rowspan="2">This Make and Model</th> <th rowspan="2">Airplane Single Engine</th> <th rowspan="2">Airplane Multi-Engine</th> <th rowspan="2">Night</th> <th colspan="2">Instrument</th> <th rowspan="2">Rotorcraft</th> <th rowspan="2">Glider</th> <th rowspan="2">Lighter Than Air</th> </tr> <tr> <th>Actual</th> <th>Simulated</th> </tr> <tr> <td>Total Time</td> <td>5564</td> <td>3368</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Pilot In Command(PIC)</td> <td></td> <td>3368</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Instructor</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 90 Days</td> <td></td> <td></td> <td>153</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 30 Days</td> <td></td> <td></td> <td>30</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Last 24 Hours</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>						- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Actual	Simulated	Total Time	5564	3368									Pilot In Command(PIC)		3368									Instructor											Last 90 Days			153								Last 30 Days			30								Last 24 Hours										
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night							Instrument					Rotorcraft	Glider	Lighter Than Air																																																																	
						Actual	Simulated																																																																													
Total Time	5564	3368																																																																																		
Pilot In Command(PIC)		3368																																																																																		
Instructor																																																																																				
Last 90 Days			153																																																																																	
Last 30 Days			30																																																																																	
Last 24 Hours																																																																																				
Seatbelt Used? Yes		Shoulder Harness Used? Yes		Toxicology Performed?																																																																																
				Second Pilot? Yes																																																																																
Flight Plan/Itinerary																																																																																				
Type of Flight Plan Filed: IFR																																																																																				
Departure Point		State	Airport Identifier	Departure Time	Time Zone																																																																															
Same as Accident/Incident Location				1710	CDT																																																																															
Destination		State	Airport Identifier																																																																																	
ATLANTA		GA	ATL																																																																																	
Type of Clearance: IFR																																																																																				
Type of Airspace: Class B																																																																																				
Weather Information																																																																																				
Source of Briefing: Company; Commercial Weather Service																																																																																				
Method of Briefing:																																																																																				

 National Transportation Safety Board FACTUAL REPORT AVIATION			NTSB ID: CHI95IA119		
			Occurrence Date: 04/07/1995		
			Occurrence Type: Incident		
Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
ORD	1652	CDT	650 Ft. MSL	0 NM	0 Deg. Mag.
Sky/Lowest Cloud Condition: Unknown				0 Ft. AGL	Condition of Light: Day
Lowest Ceiling: Overcast			1500 Ft. AGL	Visibility: 4 SM	Altimeter: 29.00 "Hg
Temperature: 6 °C		Dew Point: 3 °C	Wind Direction: 40		Density Altitude: Ft.
Wind Speed: 16		Gusts:	Weather Conditions at Accident Site: Visual Conditions		
Visibility (RVR): 0 Ft.		Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown		
Restrictions to Visibility: Haze					
Type of Precipitation: None					
Accident Information					
Aircraft Damage: Minor			Aircraft Fire: None		Aircraft Explosion: None
Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				3	3
Other Crew					
Passengers				111	111
- TOTAL ABOARD -				116	116
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	116	116

 <p>National Transportation Safety Board</p> <p>FACTUAL REPORT</p> <p>AVIATION</p>	NTSB ID: CHI95IA119	
	Occurrence Date: 04/07/1995	
	Occurrence Type: Incident	
Administrative Information		
<p>Investigator-In-Charge (IIC)</p> <p>MATTHEW L. THOMAS</p>		
<p>Additional Persons Participating in This Accident/Incident Investigation:</p> <p>JEFFREY BARNETT FAA ORD FSDO CHICAGO, IL</p> <p>ANTHONY C SKIPPER TIMKEN; 1835 DUEBER AVE, SW CANTON, OH 44708</p> <p>RICHARD B JANKOWSKI ALLIED LNDG SYS; 3520 WESTMOOR SOUTH BEND, IN 46628</p> <p>RUSSELL C WONG UAL SFOEG; SFO INTL AIRPORT SAN FRANCISCO, CA 94128</p>		
<p>FACTUAL REPORT - AVIATION</p> <p>Page 5</p>		