Ground collision between a Boeing 747-300, PH-BUL, and Boeing 767, April 20, 1997, at Houston.

Micro-summary: A Boeing 747 collided with a Boeing 767 on the ground.

Event Date: 1997-04-20 at 1615 CDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board	NTSB	ID: FTW97IA16	31	Aircraft Registi	Aircraft Registration Number: PHBUL Most Critical Injury: None					
FACTUAL REPORT	Occurr	ence Date: 04/2	0/1997	Most Critical Ir						
AVIATION	ence Type: Incic	lent	Investigated B	Investigated By: NTSB						
Location/Time										
Nearest City/Place	State	Zip Code	Local Time	Time Zone						
HOUSTON	TX	77059	1615	CDT						
Airport Proximity: On Airport	n Landing Facility	:	Direction Fro	Direction From Airport:						
Aircraft Information Summary										
Aircraft Manufacturer	Model/Serie	es		Type of Aircraft						
Boeing	747-300			Airplane						
Sightseeing Flight: No		Air Medical T	Air Medical Transport Flight: No							

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On April 20, 1997, at 1615 central daylight time, a Boeing 747-300 airplane, Dutch registration PHBUL, collided with another airplane while taxiing for takeoff at the Houston Intercontinental Airport, near Houston, Texas. The airplane was being operated by the Royal Dutch Airlines as KLM Flight 662 under Tittle 14 CFR Part 129, at the time of the incident. None of the 284 passengers, 10 flight attendants, or the 5 flight crewmembers were injured. Visual meteorological conditions prevailed for the scheduled international flight for which an IFR flight plan was filed. KLM Flight 662 was originating at the time of the incident, with Amsterdam, The Netherlands, at its intended destination.

According to Air Traffic Control (ATC) personnel at the airport, an Air France Boeing 767 was number one in sequence for takeoff at the runup area for runway 14L. The Air France flight reported to ATC that they were not ready for takeoff; however, they did not state the reason for their delay. ATC asked KLM flight 662, which was number two for departure, if they were able to taxi around the Air France Boeing 767 which was standing on the right side of the KLM Boeing 747. The KLM crew answered that they were able to taxi around and they were subsequently cleared by ATC to taxi into position and hold for departure on 14L.

The first officer of the KLM 747 stated that the flight crew was aware of the close clearance between the two wing tips and they "taxied slowly and cautiously" slightly to the left of the yellow taxi line. The first officer stated that he remarked "we were clear" as he watched out his window on the right side of the cockpit. A couple seconds after the "all clear" the crew reported that a "slight bump" was felt which they attributed to a bump on the taxiway.

While taxiing around the standing Air France Boeing 767, the extended right outboard leading edge flap from the KLM 747 impacted the left wing tip of the Air France 767, resulting in minor damage to both airplanes. The flight crew of the Air France's 767 reported the collision to ATC by radio.

Airport operations personnel reported that no fuel was spilled from either aircraft and both airplanes taxied back to their respective gates in the international ramp where all passengers were deplaned without further incident. Air France's maintenance personnel replaced the left wing navigation light assembly from the Boeing 767 and the airplane was released, departing Houston approximately 3 hours after the their scheduled departure time.

Damage to the KLM Boeing 747 was limited to the leading edge of the outboard leading edge flap and the flap actuator. According to the FAA inspector at the site, the wing tip is visible from the first officer's station in the cockpit of the 747. Additionally, the FAA inspector reported that the side window was crazed.

The scheduled departure time for KLM Flight 662 was 1540. The visibility at the time of the

TRANSP
National Transportation Safety Board
0 7
FACTUAL REPORT
7 >
AVIATION

NTSB ID: FTW97IA161

Occurrence Date: 04/20/1997

TAC TOAL RETORT	Occurrence Date: 04/20/1991	
AVIATION	Occurrence Type: Incident	
Narrative (Continued)		
incident was reported in excess of 1	.0 nautical miles without restric	ctions.

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: FTW97IA161

Occurrence Date: 04/20/1997

AVIATION				.,_0, . 501									
			Occurrence Type: Incident										
Landing Facility/Approach Information													
Airport Name	Airport ID:	А	irport Elevatio	n	Runway Used Ru			ay Lengt	h	Runw	ay Width		
HOUSTON INTERCONTINENTAL IA					98 Ft. M	/ISL	14F	₹	10		100		
Runway Surface Type: Asphalt													
Runway Surface Condition: Dry													
Type Instrument Approach:													
VFR Approach/Landing:													
Aircraft Information													
Aircraft Manufacturer			Mode							Serial	l Number		
Boeing			747-	-300									
Airworthiness Certificate(s): Transport													
Landing Gear Type: Retractable - Tricycle													
Homebuilt Aircraft? No	Number of Seats:		Certifi	Certified Max Gross Wt.				LBS Numbe			er of Engines: 4		
Engine Type: Turbo Jet	Engine M P&W	Engine Manufacturer: Model/Series: JT9D-7A							Rated Power: 45000 LBS				
- Aircraft Inspection Information													
Type of Last Inspection	Date of La	Date of Last Inspection Time Sind			nce Last Insp		Airframe Total Time						
Continuous Airworthiness									ours	Hours			
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? Yes	ELT Operate	ed? No			ı	ELT A	Aided ii	n Locating A	ccident S	Site?			
Owner/Operator Information													
Registered Aircraft Owner			Street	Add	ress 565 TAXTE	ER R	OAD						
J.H. MEURER			City								State		Zip Code
	ELMSFORD NY Street Address										10523		
Operator of Aircraft			Street	Auui	Same as R	Reg'd	Aircra	aft Owner					
Same as Reg'd Aircraft Owner	City							State Zip Code					
Operator Does Business As: ROYAL DUTCH AIRLINES Operator Designator Code: KLM													
- Type of U.S. Certificate(s) Held:	None												
Air Carrier Operating Certificate(s)	:												
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 129: Foreign													
Type of Flight Operation Conducted: Scheduled; International; Passenger/Cargo													
]	FACTI	JAL REPO	ORT	- AVIATIO	N							Page 2
		\				*							-

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW97IA161

Occurrence Date: 04/20/1997

AVIATION				Occurrence Type: Incident				1							
First Pilot	Information														
Name	City						tate Date of		rth	Age					
On File On Fi							ile					File	On File		40
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot										Cert	tificate	e Numb	per: On F	ile	
Certificate(s): Airline Transport															
Airplane Ra	ating(s): Multi	i-engine Lar	nd; Single-e	ngine Land											
Rotorcraft/0	Glider/LTA: None	e	-	-											
Instrument Rating(s): Airplane															
Instructor Rating(s): None															
Type Rating/Endorsement for Accident/Incident Aircraft? Yes Current Biennial Flight Review?															
Medical Ce	rt.: Class 1	Medica	al Cert. Status	s: Valid Me	dicalno w	aivers/l	im.		Da	te of La	st Me	dical E	xam: 01/	1997	
- Flight Tim	- Flight Time Matrix		This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nig	ht	Actual	Instrument Simulate		Rotorcraft		Glider		Lighter Than Air
Total Time	Total Time		1800												
Pilot In Cor	Pilot In Command(PIC)														
Instructor															
Last 90 Day	Last 90 Days		152												
Last 30 Day	Last 30 Days		42												
Last 24 Ho	urs	L	10			<u> </u>									
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes	1		Toxico	ology Per	formed	l? No		S	econd Pilo	t? Ye	S
Flight Pla	n/Itinerary														
Type of Flig	ht Plan Filed: IF	R													
Departure F	Point						State	P	Airport Identifier		er Departure		rture Time	1	Time Zone
Same as	Accident/Incide	nt Location						ı	IAH			1615			CDT
Destination							State	State Airport Ident		dentifie	r				
AMSTERDAM							OF	EHAM							
Type of Cle	earance: IFR					•		•							
Type of Air	space: Class	В													
Weather	Information														
Source of I	Briefing: Compa	any													
Method of	Briefing:														
FACTUAL REPORT - AVIATION Page 3											Page 3				
									_					_	

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: FTW97IA161

Occurrence Date: 04/20/1997

Occurrence Type: Incident

Weather Information WOF ID **Observation Time** Time Zone **WOF Elevation** WOF Distance From Accident Site Direction From Accident Site CDT IAH 1553 98 Ft. MSL 320 Deg. Mag. 3500 Ft. AGL Sky/Lowest Cloud Condition: Scattered Condition of Light: Day Lowest Ceiling: Broken 7500 Ft. AGL 10 29.00 Visibility: SM Altimeter: "Hg Temperature: 27 °C Dew Point: 17 °C Wind Direction: 210 Density Altitude: Ft. Weather Condtions at Accident Site: Visual Conditions Wind Speed: 4 Gusts: Visibility (RVR): 0 Ft. Visibility (RVV) 0 SM Intensity of Precipitation: Unknown Restrictions to Visibility: None None Type of Precipitation: **Accident Information** Aircraft Damage: Minor Aircraft Fire: None Aircraft Explosion None Classification: Foreign Registered/U.S. Soil - Injury Summary Matrix Fatal Serious Minor None TOTAL First Pilot 1 1 1 Second Pilot Student Pilot Flight Instructor Check Pilot Flight Engineer 1 1 10 10 Cabin Attendants Other Crew 2 2 284 Passengers 284 - TOTAL ABOARD -299 299 Other Ground 0 0 0 0 - GRAND TOTAL -0 0 0 299 299

National Transportation Safety Board

FACTŲAL REPORT AVIATION

NTSB ID: FTW97IA161

Occurrence Date: 04/20/1997

Occurrence Type: Incident

Investigator-In-Charge (IIC)

HECTOR R. CASANOVA

Additional Persons Participating in This Accident/Incident Investigation:

SIDNEY P ALEXANDER FAA FSDO HOUSTON, TX 77059

JAVIER CAMBA ROYAL DUTCH AIRLINES HOUSTON, TX 77059