
90 degree nosewheel rotation on landing, Airbus A320, February 16, 1999

Micro-summary: This Airbus A320 landed with the nose gear rotated at a 90 degree angle.

Event Date: 1999-02-16 at 1602 EST


Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC
All rights reserved.
www.fss.aero

		NTSB ID: NYC99IA062		Aircraft Registration Number: N628AW	
		Occurrence Date: 02/16/1999		Most Critical Injury: None	
		Occurrence Type: Incident		Investigated By: NTSB	
Location/Time					
Nearest City/Place COLUMBUS		State OH	Zip Code 43219	Local Time 1602	Time Zone EST
Airport Proximity: On Airport		Distance From Landing Facility:		Direction From Airport:	
Aircraft Information Summary					
Aircraft Manufacturer Airbus Industrie		Model/Series A-320-231		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On February 16, 1999, at 1602 Eastern Standard Time, an Airbus A-320-231, N628AW, operated by America West Airlines as flight 2811, received minor damage when it landed at Port Columbus International Airport (CMH), Columbus, Ohio, with the nose wheels rotated 90 degrees. There were no injuries to the 2 certificated pilots, 3 flight attendants and 26 passengers. Visual meteorological conditions prevailed for the scheduled passenger flight which had departed from Newark (EWR), New Jersey, about 1404. Flight 2811 was operated on an instrument flight rules flight plan conducted under 14 CFR Part 121.</p> <p>According to statements from the flight crew, flight 2811 was uneventful until the landing gear was lowered prior to landing at CMH. After the landing gear was extended to the down-and-locked position, the flight crew received indications of dual landing gear control and interface unit (LGCIU) faults.</p> <p>The flight crew entered into a holding pattern and attempted to troubleshoot the faults; however, they were unable to determine the source of the problem. The flight crew then prepared for a landing at CMH, with nosewheel steering and thrust reversers inoperative due to the faults. During the final approach, at the flight crew's request, the control tower performed a visual check of the landing gear, which revealed that the nosewheels were rotated about 90 degrees.</p> <p>The flight crew then initiated a missed approach and declared an emergency. The cabin crew was notified of an impending emergency landing, and the cabin and passengers were prepared for the landing. The captain initiated the approach, and described the touchdown as soft. The airplane stopped on the 10,250-foot-long runway with about 2,500 feet of runway remaining. Damage was limited to the nose landing gear tires and rims.</p> <p>The captain reported that after landing, he noticed smoke was drifting up on the right side of the airplane. He said he attempted to contact the control tower and confirm if a fire was present, but was unable due to frequency congestion. He then initiated an emergency evacuation using the left and right side overwing exits.</p> <p>A review of the air/ground communications, as recorded by the Columbus Air Traffic Control Tower, did not reveal a congested frequency when the emergency evacuation was initiated.</p> <p>According to Airbus, nose wheel steering was hydraulically actuated through either the cockpit tiller and/or the rudder pedals.</p> <p>A post-incident visual inspection of the nose landing gear assembly revealed no anomalies. The steering control module was replaced, and a subsequent functional check of the nosewheel steering was successful.</p>					
FACTUAL REPORT - AVIATION					
					Page 1

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: NYC99IA062

Occurrence Date: 02/16/1999

Occurrence Type: Incident

Narrative (Continued)

The steering control module was a sealed unit, opened only during overhaul, with no specified overhaul time, and had accumulated 3,860 hours since last overhauled on March 3, 1998. It was shipped to Messier-Bugatti, the manufacturer, and examined under the supervision of the French Bureau Enquetes Accidents (BEA). The examination revealed that the external hydraulic O-ring seals on the steering control module's selector valve were extruded (distorted out of the seal's groove). A small offset was found in the steering control valve.


Airbus further reported that while the offset would have been measurable, it would not have been noticeable under normal operations. Additionally, during landing gear extension, the brake and steering control unit (BSCU) would have been energized and hydraulic pressure would have been directed toward the steering servo valve. The BSCU would have then commanded a small rotation of the nose wheel to check for proper movement. Any disagreement between the commanded position and actual position of the nose wheel would have deactivated the nose wheel steering. However, if hydraulic pressure had bypassed the steering control valve, there would have been continued pressurization to the servo valve, and because of the servo valve's inherent offset, in-flight rotation of the nose wheels.


Procedures existed for removal of hydraulic pressure from the steering control module. However, once the nosewheel strut had deflected 90 degrees, the centering cam would have been rotated to a flat area, and would have been incapable of overriding the 3,000 PSI hydraulic system, and returning the nose wheels to a centered position.

Documents from Airbus indicated there have been three similar incidents in which A320 airplanes landed with the nose wheels rotated about 90 degrees. Examination of the steering control modules on two of the airplanes revealed extrusion of the selector valve's external seals similar to that found on N628AW. Airbus had attributed the extrusion failures to the lack of a backup seal or the effects of aging on the seals. As a result of these incidents, Airbus issued Service Bulletin (SB) A320-32-1197 on October 8, 1998, to recommend replacement of the external seals on the steering control module's selector valve on A320 and A321 airplanes within 18 months of the SB's issuance.

At the time of the incident, neither the French Direction General de l'Aviation Civile (DGAC), or the Federal Aviation Administration (FAA), had adopted the service bulletin as an airworthiness directive. The operator was not required to comply with the service bulletin, and had not complied with it.

On March 24, 1999, the DGAC issued Airworthiness Directive (AD) 1999-124-129(B) to require compliance with the SB. On December 17, 1999, the FAA issued AD 99-23-09 which was based upon the French AD, with a 12 month time of compliance for modification of the nose wheel steering control valve.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: NYC99IA062				
		Occurrence Date: 02/16/1999				
		Occurrence Type: Incident				
Landing Facility/Approach Information						
Airport Name PORT COLUMBUS INTL ARPT		Airport ID: CMH	Airport Elevation 815 Ft. MSL	Runway Used 28L	Runway Length 10250	Runway Width 150
Runway Surface Type: Asphalt						
Runway Surface Condition: Dry						
Type Instrument Approach: Visual						
VFR Approach/Landing: None						
Aircraft Information						
Aircraft Manufacturer Airbus Industrie		Model/Series A-320-231		Serial Number 67		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 154	Certified Max Gross Wt. 162068 LBS		Number of Engines: 2	
Engine Type: Turbo Fan		Engine Manufacturer: Int'l Aero En		Model/Series: V2500-A1	Rated Power: 24800 LBS	
- Aircraft Inspection Information						
Type of Last Inspection Continuous Airworthiness		Date of Last Inspection 02/1999	Time Since Last Inspection 18 Hours		Airframe Total Time 28404 Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed? No		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner WILMINGTON TRUST CO.		Street Address RODNEY SQUARE NORTH				
		City WILMINGTON		State DE	Zip Code 19898	
Operator of Aircraft AMERICA WEST AIRLINES		Street Address 4000 EAST SKY HARBOR BLVD				
		City PHOENIX		State AZ	Zip Code 85034	
Operator Does Business As:				Operator Designator Code: AWXA		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger/Cargo						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: NYC99IA062
	Occurrence Date: 02/16/1999
	Occurrence Type: Incident

First Pilot Information

Name On File	City On File	State On File	Date of Birth	Age 43
-----------------	-----------------	------------------	---------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number:
--------	---------------------	--------------------------------------	---------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): None

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review?
---	---------------------------------

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 10/1998
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	10850									
Pilot In Command(PIC)	6000	1100								
Instructor										
Last 90 Days	141	141								
Last 30 Days	47	47								
Last 24 Hours	6	6								

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point NEWARK	State NJ	Airport Identifier EWR	Departure Time 1404	Time Zone EST
---------------------------	-------------	---------------------------	------------------------	------------------

Destination Same as Accident/Incident Location	State	Airport Identifier CMH	
---	-------	---------------------------	--


Type of Clearance: IFR

Type of Airspace: Class C

Weather Information

Source of Briefing:
Company

Method of Briefing:

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: NYC99IA062
	Occurrence Date: 02/16/1999
	Occurrence Type: Incident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
CMH	1550	EST	815 Ft. MSL	0 NM	0 Deg. Mag.
Sky/Lowest Cloud Condition: Scattered			5500 Ft. AGL	Condition of Light: Day	
Lowest Ceiling: None		0 Ft. AGL	Visibility: 10 SM	Altimeter: 29.00 "Hg	
Temperature: 15 °C	Dew Point: 6 °C	Wind Direction: 210		Density Altitude: Ft.	
Wind Speed: 16	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information		
Aircraft Damage: Minor	Aircraft Fire: None	Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil					
- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				3	3
Other Crew					
Passengers				26	26
- TOTAL ABOARD -				31	31
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	31	31

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB

NTSB ID: NYC99IA062

Occurrence Date: 02/16/1999

Occurrence Type: Incident

Administrative Information

Investigator-In-Charge (IIC)

ROBERT L. HANCOCK

Additional Persons Participating in This Accident/Incident Investigation:

RUSSELL HAYDEN
FAA FSDO
COLUMBUS, OH

JACK DRAKE
AMERICA WEST AIRLINES
PHOENIX, AZ

JEAN PAUL DE VILLENEUVE
BUREAU ENQUETES-ACCIDENTS
LE BOURGET, FR,

MARTEN BOSMAN
AIRBUS INDUSTRIES
TOLUSE, FR,