
Bird ingestion into both engines, Douglas DC-9-15F, March 4, 1999

Micro-summary: This Douglas DC-9-15F injected birds into both engines while on final approach.

Event Date: 1999-03-04 at 2200 CST

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: <http://www.nts.gov/>

Cautions:

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: CHI99FA102		Aircraft Registration Number: N195US	
		Occurrence Date: 03/04/1999		Most Critical Injury: None	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place KANSAS CITY		State MO	Zip Code 64195	Local Time 2200	Time Zone CST
Airport Proximity: Off Airport/Airstrip		Distance From Landing Facility: 3		Direction From Airport: 10	
Aircraft Information Summary					
Aircraft Manufacturer Douglas		Model/Series DC-9-15F		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
HISTORY OF FLIGHT					
<p>On March 4, 1999, at 2200 central standard time, a Douglas DC-9- 15F, N195US, operated by USA Jet Airlines, Incorporated, encountered a flock of large birds, while on final approach for landing at Kansas City International Airport, Kansas City, Missouri. During the encounter, several birds were ingested into both engines, resulting in a severe power loss. The pilot managed to regain enough thrust on one engine to continue the approach and land the airplane without further incident. Night visual meteorological conditions prevailed at the time of the encounter. The flight was being conducted under 14 CFR Part 121, non-scheduled, domestic air cargo service. An IFR flight plan was on file. The captain and first officer reported no injuries. The flight originated at Los Angeles, California, at 1825 pacific standard time (pst), and was en route to Kansas City, Missouri.</p> <p>In her written statement, the first officer said that she was the flying pilot for this leg of their trip. Kansas City International Airport was conducting visual approaches to runways 19L and 19R. The airplane was cleared to land on runway 19R (10,801 feet by 150 feet, dry concrete). The first officer said that the airplane was on speed and course for the visual approach. "The captain had just called the 1,000 feet [above the ground] call when a flock of snow geese [was] suddenly illuminated in our lights, engulfing us from below, flying into us. No birds hit the windshields, but it was immediately apparent they had flown into the engines." The captain said that he had the airplane and directed the first officer to set the flaps to 30 degrees. The first officer said that she notified the Kansas City Air Traffic Control Tower (ATCT) of the bird strike. "When asked by [the] tower if we wanted to go around, we responded, negative.</p> <p>The number two engine showed about 30 percent N1. The number one engine, when full thrust [was] applied, responded with fluctuating EPRs (engine pressure ratio gauge indications) and violent vibrations. We were able to land and taxi to the ramp with the thrust from [the] number one engine."</p> <p>In his written statement, the captain said that on the descent into Kansas City international Airport, they received the current airport Automatic Terminal Information System (ATIS) broadcast. The ATIS information included the note, "migratory bird activity reported in the vicinity of the airport." Descending through 10,000 feet mean sea level (msl), the airplane's ground flood lights were turned on. Descending through 5,000 feet msl, the airplane's landing lights were turned on. The captain said that the first officer was flying the airplane on a 150 degree magnetic heading for the visual approach. The first officer intercepted the localizer inbound course for runway 19R, just inside the final approach fix. Ten miles from the airport, the landing gear was extended and the flaps lowered to 40 degrees. At 1,000 feet above ground level (agl), the captain said he made the call, "on localizer, on glide path, on speed." "At 800 feet agl, we hit with no warning, a large flock of snow geese." The captain said that the airplane was three miles from the runway threshold. "Both engines compressor stalled, and I took control of [the] aircraft." The airspeed</p>					
FACTUAL REPORT - AVIATION					
					Page 1

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: CHI99FA102

Occurrence Date: 03/04/1999

Occurrence Type: Accident

Narrative (Continued)

decayed and the airplane descended below the glide path. The captain advanced the power on both engines and ordered the flaps reset to 30 degrees, the single-engine flap position. "The number one engine continued to compressor stall. The number two engine went to a sub-idle run condition."

The captain said that the number one engine compressor stalled at a rate of a surge/stall per second, and vibrated violently. The number two engine remained at 30 percent N1 with no response to the throttle position. The captain reduced the power on the number one engine "enough to lessen the surge/stall condition to a rate of once every two seconds, which allowed just enough thrust to maintain the approach and to lower the vibration... The number one engine continued to compressor stall/surge to touchdown." The touchdown was normal.

PERSONNEL INFORMATION

The captain holds an airline transport pilot certificate with single-engine land, multi-engine land, and instrument airplane ratings. The captain reported having over 16,000 total flight hours, and over 10,000 hours in the DC-9. In the 30 days prior to the flight, he had logged 60 hours, all in the DC-9.

USA Jet Airlines, Incorporated, stated the captain underwent a flight proficiency check in the DC-9 on December 19, 1998.

The first officer holds an airline transport pilot certificate with single-engine land, multi-engine land, and instrument airplane ratings. The first officer reported having over 4,000 hours total flight time, and over 400 hours in the DC-9. In the 30 days prior to the flight, she had logged 60 hours, all in the DC-9.

USA Jet Airlines, Incorporated, stated the first officer underwent a flight proficiency check in the DC-9 on August 20, 1998.

AIRCRAFT INFORMATION

The airplane was a Douglas DC-9-15F, N195US, serial number 47017, owned and operated by USA Jet Airlines, Incorporated, of Belleville, Michigan, and was used for commercially transporting manufactured parts for automobiles, and other on-demand cargo.

The airplane had undergone a company continuous airworthiness inspection, "C" check, on February 4, 1999. The total airframe time at the inspection was 68,213.5 hours. The airframe time at the time of the bird encounter was 68,261.2 hours.

The airplane underwent a standard preflight by the crew prior to departing Los Angeles on March 4, 1999.

AIRPORT INFORMATION

Kansas City International Airport (MCI) is located at Latitude 39 degrees, 17.86 minutes north, and Longitude 94 degrees, 42.84 minutes west. The airport center is located approximately 15 miles north-northwest of the Kansas City metropolitan area, and 11 miles due north of the Missouri River. The Missouri River runs west-southwest to east through the north part of the city.

The FAA operates a class B airspace over the airport which extends radially from the airport center, out to 20 nautical miles. Requirements for operating with a mode C transponder extends radially for 30 nautical miles.

Airport Remarks listed for Kansas City International Airport in the Airport/Facilities Directory, North Central U. S., covering Missouri, include an advisory for "Waterfowl on and in vicinity of airport from October 1 to December 15, and April 1 to May 30."

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: CHI99FA102

Occurrence Date: 03/04/1999

Occurrence Type: Accident

Narrative (Continued)

WRECKAGE AND IMPACT INFORMATION

On March 5, 1999, at 0930 cst, Federal Aviation Administration (FAA) inspectors examined the airplane at Executive Beechcraft, Kansas City International Airport.

The airframe showed no damage. Traces of bird remains were found along the front and top of the left nose gear door, and the left nose gear brace strut.

The left engine (number one engine), serial number 649193, showed traces of bird remains on the nose dome. Traces of bird remains were also observed adhering to the front ring and inside wall of the engine's nose cowl. The inlet guide vanes showed some minor inward denting along the leading edges. All of the first stage compressor fan blades were bent and broken. The second stage compressor fan blades were also bent and broken. Bird remains were observed adhering to the inner wall of the engine's exhaust pipe.

The predominately intact carcass of a large white-feathered bird was found embedded on the inboard inlet guide vanes of the airplane's right engine (number two engine), serial number 654749. Traces of bird remains were observed at the base of the nose dome, next to the bird carcass.

Flight control continuity was confirmed. Examination of the airplane's remaining systems revealed no anomalies.

The engines were retained for further examination.

TESTS AND RESEARCH

The left engine (number one engine), serial number 649193, and the right engine (number two engine), serial number 654749, were shipped to Israel Aircraft Industries (IAI), Bedek Aviation Group, Ben Gurion International Airport, Tel Aviv, Israel, for disassembly, inspection, and repair.

Both engines were examined on May 3, 1999. The examination was overseen by the State of Israel, Ministry of Transport, Civil Aviation Administration, at the request of the NTSB.

The examination of the left engine (649193) revealed heavy damage to most of the blades (75 to 100 percent) in the 13 compressor disks, and to stators C2 through C12. The inlet fan case and exit stator vanes were destroyed. Melted metal particles were found sprayed and adhering to the number one turbine disk and nozzle guide vanes, and inside walls of the exhaust case.

The examination of the right engine (654749) revealed moderate damage to all of the blades in the C1 and C2 disks. There was minor damage to the 13th stage compressor disk. No other damage was revealed.

At the request of the NTSB, Geo-Marine, Incorporated, of Panama City, Florida, contractor for the U. S. Air Force's Bird Aircraft Strike Hazard (BASH) program, was asked to assess the level of bird activity in the vicinity of the Kansas City International Airport, on March 4, 1999, around the time of the encounter. Geo-Marine operates the Avian Hazard Advisory System (AHAS), which is designed to track bird migration patterns, in near real time, using next-generation weather radar (NEXRAD) images from the NEXRAD Information Distribution System, and determine if that activity constitutes a hazard to aircraft. NEXRAD Level II archive tapes from the WSR-88D radar, located at Pleasant Hill, Missouri, 30 nautical miles southeast of the Kansas City International Airport, for March 4, 1999, were retrieved and compared with National Weather Service information to determine the likelihood of biological targets in the area during the time when the bird strike occurred. Analysis of the radar display information showed a wide area of returns consistent with a widespread northerly migration of birds. The broad-front nature of the returns indicated a large-scale migration. The overall density and pattern of targets in the reflectivity image

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: CHI99FA102
	Occurrence Date: 03/04/1999
	Occurrence Type: Accident

Narrative (Continued)

suggested a migration of waterfowl through the area. A report provided by Geo-Marine, Incorporated, is attached as an addendum to this report.

ADDITIONAL INFORMATION

As a result of facts gathered during this investigation, added to findings from other airplane accidents involving encounters with birds, the National Transportation Safety Board put forth the following recommendations:

The FAA evaluate the potential for using Avian Hazard Advisory System (AHAS) technology for bird strike risk reduction in civil aviation, and if found feasible, implement such a system in high-risk areas, such as major hub airports, and along migratory bird routes, nationwide.

In coordination with the U. S. Department of Agriculture, the FAA conduct research to determine the effectiveness and limitations of existing and potential bird hazard reduction technologies.

In consultation with the U. S. Department of Agriculture, the FAA require that wildlife assessments be conducted at all 14 Code of Federal Regulation Part 139 airports where such assessments have not already been conducted.

The FAA require the development of a wildlife management program for all airports determined to need one as the result of the wildlife hazard assessment proposed in the previous recommendation.

The FAA ensure that the wildlife hazard management programs are incorporated into the airport certification manuals and periodically inspect the programs' progress.

The FAA require all airplane and airport operators to report bird strikes.

The FAA contract with an appropriate agency to provide proper identification of bird remains, establish timely procedures for proper bird species identification, and ensure that airport and aircraft maintenance employees are familiar with the procedures.

Before allowing high-speed, low-level airplane operations, the FAA evaluate the potential risk of increased bird strike hazards to air carrier turbo-jet airplanes.

With representatives from the U. S. Department of Agriculture, the Department of the Interior, the Department of Defense, and the U. S. Army Corps of engineers, the FAA convene a task force to establish a permanent bird strike working group to facilitate conflict resolution and improve communications between aviation safety agencies and wildlife conservation interests.

The U. S. Department of Agriculture participate in a task force, to be convened by the FAA, to establish a permanent bird strike working group to facilitate conflict resolution and improve communications between aviation safety agencies and wildlife conservation interests.

The U. S. Army Corps of Engineers participate in a task force, to be convened by the FAA, to establish a permanent bird strike working group to facilitate conflict resolution and improve communications between aviation safety agencies and wildlife conservation interests.

The U. S. Department of Defense participate in a task force, to be convened by the FAA, to establish a permanent bird strike working group to facilitate conflict resolution and improve communications between aviation safety agencies and wildlife conservation interests.

The U. S. Department of the Interior participate in a task force, to be convened by the FAA, to establish a permanent bird strike working group to facilitate conflict resolution and improve communications between aviation safety agencies and wildlife conservation interests.

National Transportation Safety Board

FACTUAL REPORT

AVIATION

SAFETY BOARD

NTSB ID: CHI99FA102

Occurrence Date: 03/04/1999

Occurrence Type: Accident

Narrative (Continued)

USA Jet Airlines, Incorporated, estimated that the cost of repairs to the left engine (649193) from damage related to the bird strike was \$550,000. The cost to repair the right engine (654749) was \$60,000. The estimated sum total cost of repairs to the DC-9 airplane, N195US, tied directly to the bird strike was \$775,000.

Parties to the investigation were the Federal Aviation Administration Flight Standards District Office, Kansas City, Missouri, USA Jet Airlines, Incorporated, Belleville, Michigan, and Pratt and Whitney, Hartford, Connecticut.

The airplane and engines were released and returned to USA Jet Airlines, Incorporated.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CHI99FA102				
		Occurrence Date: 03/04/1999				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name KANSAS CITY INTERNATIONAL		Airport ID: MCI	Airport Elevation 1026 Ft. MSL	Runway Used 19R	Runway Length 10801	Runway Width 150
Runway Surface Type: Concrete						
Runway Surface Condition: Dry						
Type Instrument Approach: Visual						
VFR Approach/Landing: Full Stop; Straight-in						
Aircraft Information						
Aircraft Manufacturer Douglas		Model/Series DC-9-15F		Serial Number 47017		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Homebuilt Aircraft? No		Number of Seats: 5	Certified Max Gross Wt. 91700 LBS		Number of Engines: 2	
Engine Type: Turbo Jet		Engine Manufacturer: P&W		Model/Series: JT8D-7B	Rated Power: 14000 LBS	
- Aircraft Inspection Information						
Type of Last Inspection Continuous Airworthiness		Date of Last Inspection 02/1999	Time Since Last Inspection 48 Hours		Airframe Total Time 2725 Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed? No		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner USA JET AIRLINES, INC.		Street Address HANGAR 2064, D STREET				
		City BELLEVILLE		State MI	Zip Code 48111	
Operator of Aircraft Same as Reg'd Aircraft Owner		Street Address Same as Reg'd Aircraft Owner				
		City		State	Zip Code	
Operator Does Business As: USA JET AIRLINES, INC.				Operator Designator Code: Y2PA		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Non-scheduled; Domestic; Cargo						
FACTUAL REPORT - AVIATION						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: CHI99FA102
	Occurrence Date: 03/04/1999
	Occurrence Type: Accident

First Pilot Information

Name On File	City On File	State On File	Date of Birth On File	Age 53
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: None

Instrument Rating(s): Airplane

Instructor Rating(s): None

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review?
---	---------------------------------

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--w/ waivers/lim.	Date of Last Medical Exam: 09/1998
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	16000	10000		16000		6000				
Pilot In Command(PIC)	5000	5000				5000				
Instructor										
Last 90 Days	150	150		150						
Last 30 Days	60	60		60						
Last 24 Hours	5	5		5						

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

Flight Plan/Itinerary

Type of Flight Plan Filed: IFR

Departure Point LOS ANGELES	State CA	Airport Identifier LAX	Departure Time 1825	Time Zone PST
--------------------------------	-------------	---------------------------	------------------------	------------------

Destination Same as Accident/Incident Location	State	Airport Identifier MCI	
---	-------	---------------------------	--

Type of Clearance: IFR

Type of Airspace: Class B

Weather Information

Source of Briefing: National Weather Service

Method of Briefing:

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: CHI99FA102
	Occurrence Date: 03/04/1999
	Occurrence Type: Accident

Weather Information

WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
MCI	2153	CST	1026 Ft. MSL	3 NM	190 Deg. Mag.
Sky/Lowest Cloud Condition: Unknown			0 Ft. AGL	Condition of Light: Night/Dark	
Lowest Ceiling: Broken		9000 Ft. AGL		Visibility: 10 SM	Altimeter: 29.00 "Hg
Temperature: 12 °C	Dew Point: -3 °C	Wind Direction: 150		Density Altitude: 991 Ft.	
Wind Speed: 8	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): 0 Ft.	Visibility (RVV) 0 SM	Intensity of Precipitation: Unknown			
Restrictions to Visibility: None					
Type of Precipitation: None					

Accident Information

Aircraft Damage: Substantial	Aircraft Fire: None	Aircraft Explosion: None
------------------------------	---------------------	--------------------------

Classification: U.S. Registered/U.S. Soil

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants					
Other Crew					
Passengers					
- TOTAL ABOARD -				2	2
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	2	2

National Transportation Safety Board

FACTUAL REPORT

AVIATION



NTSB ID: CHI99FA102

Occurrence Date: 03/04/1999

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

DAVID C. BOWLING

Additional Persons Participating in This Accident/Incident Investigation:

JERRY L MCCORMACK
FAA-10015 N. EXECUTIVE HILLS
KANSAS CITY, MO 64153

RENEE GREGORY
USA JET-HANGAR 2064 D STREET
BELLEVILLE, MI 48111

MICHAEL L YOUNG
PRATT & WHITNEY-400 MAIN ST.
HARTFORD, CT 06108