Turbulence injury, McDonnell Douglas DC-9-51, July 25, 2001

Micro-summary: This McDonnell Douglas DC-9-51 encountered moderate turbulence during descent, breaking a passenger's ankle.

Event Date: 2001-07-25 at 1210 EDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved. www.fss.aero

National Transportation Safety Board NTSB ID: CHI01LA245 Aircraft Registration Number: N780NC FACTUAL REPORT Occurrence Date: 07/25/2001 Most Critical Injury: Serious AVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone ΜI 48242 1210 **EDT** Detroit Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft McDonnell Douglas DC-9-51 Airplane

Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On July 25, 2001, at approximately 1210 eastern daylight time, a DC-9-51, N780NC, operated by Northwest Airlines as flight 490, encountered moderate turbulence during a descent into the Detroit Metro Airport (DTW), Detroit, Michigan. One passenger suffered a broken ankle. There were no other injuries to the two flight crewmembers, three flight attendants, or to the other 91 passengers on board. The airplane did not receive any damage. The 14 CFR Part 121 flight was operating in visual meteorological conditions and an IFR flight plan was filed. The flight departed from Atlanta, Georgia, at 1048 eastern daylight time.

Air Medical Transport Flight: No

The captain reported that prior to departure the captain trainee made a passenger announcement which included the probability of turbulence along the route of flight, especially during the descent into Detroit. The captain reported that he turned on the weather radar prior to the descent into DTW. He reported the captain trainee turned on the seat belt sign and made a passenger announcement commenting that they should expect turbulence during the descent. The captain reported they encountered light turbulence when they started the descent and although there were no storm cells visible on the radar for their flight path, there was an indication of light rain.

The captain reported that he instructed the captain trainee to call the lead flight attendant to assure they were seated and strapped in as a precaution. He reported that when the trainee captain opened the door he noticed the lead flight attendant was already seated with a shoulder harness on. The captain reported they continued the descent in light turbulence and between an altitude of 18,000 feet and 12,000 feet, they encountered several moderate "bumps." He reported that approximately 30 seconds later, they were informed that an off duty flight attendant had been out of her seat when they encountered the moderate turbulence and that she had broken her ankle. The captain reported that the remainder of the flight was uneventful with little or no turbulence.

The injured off duty flight attendant reported, "Just before the descent began into Detroit, several passengers went to the lavatory and returned with no difficulty. I chose to give all other passengers the opportunity to go before I did. The flight was continuing smoothly as I made my way from my seat on the right side of the exit row, aft to the lavatory. While returning to my seat, the aircraft began to encounter some moderate turbulence as is normal while descending. I held to the seat backs to support myself as I walked forward toward my seat. As I neared my seat, the aircraft encountered a severe pocket of air with absolutely no warning whatsoever. I was lifted into the air as the aircraft dipped, then falling to the floor of the cabin. I could tell immediately that my ankle was broken because of its angle, and the terrible pain."

A review of the flight data recorder data revealed the vertical acceleration of the airplane between 14,429 feet and 11,114 feet varied between .56 g's and 1.39 g's.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI01LA245

Occurrence Date: 07/25/2001

FACIUAL REPORT	Occi	Occurrence Date: 07/25/2001											
AVIATION	urrence 7	Туре:	Accident				_		_				
Landing Facility/Approach Information													
Airport Name		Airport	ID:	Airport Eleva	tion	Run	way Used	Runwa	Runway Length		Runwa	y Width	
Wayne County		DTW		Ft.	MSL								
Runway Surface Type: Unknown													
Runway Surface Condition: Unknown													
Type Instrument Approach: Unknown													
VFR Approach/Landing: Unknown													
Aircraft Information													
Aircraft Manufacturer			lodel/S						Serial	Number	•		
McDonnell Douglas			OC-9-	51					9871				
Airworthiness Certificate(s): Transport													
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No Number of Seat	Iomebuilt Aircraft? No Number of Seats: 130					Certified Max Gross Wt.					er of Engines: 2		
Engine Type: Turbo Jet	Engine P&W		ufacturer:	Model/Series: JT8D-17 (H)					Power: 0 LBS				
- Aircraft Inspection Information													
Type of Last Inspection		Date of	Date of Last Inspection Time Si			Since Last Inspection			Airframe Total Time		l Time		
AAIP							Hours					Hours	
- Emergency Locator Transmitter (ELT) Information													
ELT Installed? No ELT Ope	ELT Installed? No ELT Operated? No					ELT Aided in Locating Accident Site? No							
Owner/Operator Information													
Registered Aircraft Owner		Str	Street Address 5101 Northwest Drive										
Northwest Airlines, Inc.		City	City							State		Zip Code	
		Stre	St. Paul N								10	13111	
Operator of Aircraft		Same as Reg'd Aircraft Owner											
Same as Reg'd Aircraft Owner	City	City						State	2	Zip Code			
Operator Does Business As: Northwest Airlines				O	perator Desig	nator Co	ode: NV	VAA	•				
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s): Flag Carrier/D	omestic												
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 121: Air Carrier													
Type of Flight Operation Conducted: Scheduled; D	Oomestic	; Passe	enger	Only									
	FACT	UAL R	EPOF	RT - AVIATI	ON							Page 2	

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: CHI01LA245

Occurrence Date: 07/25/2001

AVIATION				Occurrence Type: Accident					1					
F: (B'' (× .		Coodificing	30 Type. 710	Clucit								
First Pilot Information Name City State Date of Birth Age													1 4 9 9	
						-					n File	Date of Birth		
On File				On Fil	e 	55								
Sex: M	Seat Occupied:	Prin	cipal Profes	n Pilot		Certificate Number:								
Certificate(s): Airline Transport; Commercial														
Airplane Rat	Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA: Helicopter														
Instrument Rating(s): Airplane; Helicopter														
Instructor Rating(s): None														
Type Rating/Endorsement for Accident/Incident Aircraft? Yes Current Biennial Flight Review?														
Medical Cert	t.: Class 1	Medica	al Cert. Status	: Valid Med	dicalw/ wa	aivers/li	m.		Date o	f Last M	ledical E	xam: 03/2001		
- Flight Time	e Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigl	light Ac		nstrument Simula	ited	Rotorcraft	Glider	Lighter Than Air	
Total Time		7058	7029			ļ								
Pilot In Com	mand(PIC)					-				-				
Instructor									-	-		_		
Last 90 Days						1								
Last 30 Days		5	5							-				
				Llood? No	Jacob Na Toylor			ology Por	formed? N		le	Second Pilot? Yes		
Seatbelt Use	eu? 1 es	Snou	Ider Harness	Usea? NO			TOXICC	nogy Per	omeur N	0		econd Pilot? Ye	es	
Flight Plan	n/Itinerary													
Type of Fligh	nt Plan Filed: F	R												
Departure Po	oint						State Airport		irport Iden	port Identifier		rture Time	Time Zone	
Atlanta							GA			1048			EDT	
Destination							State	P	irport Iden	tifier				
Detroit							MI		TW					
Type of Clea	arance: IFR													
Type of Airspace: Class A														
Weather I	nformation													
Source of Briefing: Company														
Method of Briefing: Aircraft Radio; Teletype														
FACTUAL REPORT - AVIATION Page 3														

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI01LA245

Occurrence Date: 07/25/2001

Occurrence Type: Accident

	PETYBOR		Occu	пенсе гуре	Accidei	IL							
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF EI	evation	WOF D	istance Fron	n Accid	ccident Site Direction From Accident S				ite	
DTW	1154	EDT	64	0 Ft. MSL				NM Deg.					
Sky/Lowes	at Cloud Condition: Few			7000 Ft. AGL					Condition of Light: Day				
Lowest Ce	iling: Broken		18000) Ft. AGL	Visib	Visibility: 10			Altii	meter:	29.93	"Hg	
Temperatu	ıre: 26 °C	S °C Dew Point: 17 °C Wind Direction: 30 Density Altitude:						Ft.					
Wind Spee	ed: 10	Gusts:		Wea	ther Condt	ions at Accid	dent Si	ite: Visual C	ond	itions			
Visibility (R	RVR): Ft.	Visibility	(RVV)	SM	Intensit	y of Precipita	ation:						
Restrictions to Visibility: None													
Type of Precipitation: None													
Accident Information													
Aircraft Dar	mage: None		Aircra	ft Fire: Non	e: None Aircraft Ex					Explosion None			
Classificati	on: U.S. Registered/U	.S. Soil											
- Injury Su	mmary Matrix	Fatal	Serious	Minor	None	TOTAL							
First Pi	lot				1	1							
Second	d Pilot				1	1							
Studen	t Pilot												
Flight II	nstructor												
Check	Pilot												
Flight E	ngineer												
Cabin A	Attendants				3	3]						
Other C	Crew												
Passen	igers		1		91	92	1						
- TOTAL A	ABOARD -		1		96	97	1						
Other G	Ground						1						
- GRAND) TOTAL -		1		96	97	1						
		•	<u>'</u>				•						

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: CHI01LA245

Occurrence Date: 07/25/2001

Occurrence Type: Accident

							-			
Δ	dт	ını	ıctı	rativ	10	Int	^rı	മാ	tιΛ	n
$\overline{}$	um		IJΙ	au	v C		OH	III C	เเบ	

Investigator-In-Charge (IIC)

Pamela S. Sullivan

Additional Persons Participating in This Accident/Incident Investigation:

Arthur R Mueller Operations Inspector FAA 8800 Beck Road Belleville, MI 48111