

---

## Nose gear-up landing, Boeing 717-200, August 9, 2001

---

**Micro-summary:** This Boeing 717-200 experienced a nose-gear-up landing.

---

**Event Date:** 2001-08-09 at 2025 CDT

**Investigative Body:** National Transportation Safety Board (NTSB), USA

**Investigative Body's Web Site:** <http://www.nts.gov/>

---

**Cautions:**

1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
  2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. ***Your company's flight operations manual is the final authority as to the safe operation of your aircraft!***
  3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
  4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.
-

		NTSB ID: CHI01FA270		Aircraft Registration Number: N2417F	
		Occurrence Date: 08/09/2001		Most Critical Injury: None	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place Mascoutah	State IL	Zip Code 62258	Local Time 2025	Time Zone CDT	
Airport Proximity: On Airport		Distance From Landing Facility: 0		Direction From Airport: 0	
Aircraft Information Summary					
Aircraft Manufacturer Boeing		Model/Series 717-200		Type of Aircraft Airplane	
Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:					
HISTORY OF FLIGHT					
<p>On August 9, 2001, about 2025 central daylight time, a Boeing 717-200, N2417F, operated as Trans World Airlines flight number 519 from Nashville, Tennessee, to Saint Louis, Missouri, sustained substantial damage on contact with runway 14L (10,000 feet by 150 feet, grooved concrete) during an emergency landing on runway 14L at Scott Air Force Base/Midamerica Airport (BLV), near Mascoutah, Illinois. The nose gear could not be extended and the flightcrew declared an emergency. After the airplane made an emergency landing, the airplane came to rest on its nose and main landing gear. An emergency evacuation of the airplane was conducted. The scheduled domestic passenger flight was operating under 14 CFR Part 121. Visual meteorological conditions prevailed at the time of the accident. The flight was on an instrument flight rules flight plan. The 2 flightcrew members, 3 cabin crew members, and 71 passengers were not injured. One passenger was taken to the hospital for observation. The flight originated in Nashville, Tennessee, and diverted to Springfield, Illinois for weather. The diverted flight departed from Capital Airport (SPI), near Springfield, Illinois at 1820. The flight was enroute to its destination, Lambert-Saint Louis International Airport (STL), near Saint Louis, Missouri, when the emergency was declared and the flight diverted to BLV for the emergency landing.</p>					
<p>The captain stated:</p> <p>... Ramp [at SPI] was congested with military and civilian aircraft. There was construction nearby. The aircraft was marshaled to a stop on the apron clear of the terminal.</p> <p>Repeated radio requests to obtain stairs to deplane were denied due to unavailability. Flight documentation was received over ACARS [Aircraft Communication Addressing and Reporting System]. Refueling was completed. Ground personnel delivered fuel documentation through the Captain's window. Received confirmation that the aircraft was all clear below for engine start and taxi.</p> <p>Engine start was normal. After beginning taxi roll a slight bump was felt that was compatible with a rough ramp area. During taxi a pack malfunction occurred and was eliminated prior to takeoff.</p> <p>During the takeoff roll, while passing a runway intersection, a noise was heard from the forward part of the aircraft compatible with runway crossing roughness.</p> <p>Gear retraction and subsequent departure from SPI was normal.</p> <p>Flew the Rivers 2 arrival to STL. Flight was all normal until gear down on final [runway] 12R. Nose gear indicator showed red light. Cycled landing gear with red</p>					
FACTUAL REPORT - AVIATION					
Page 1					

 <p>National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION</p>	NTSB ID: CHI01FA270
	Occurrence Date: 08/09/2001
	Occurrence Type: Accident

## Narrative (Continued)

nose gear light still illuminated. Did a Fly by of tower. Tower confirmed main gear down, nose gear up. Flight went around. Got radar vector to holding area. Completed Gear Red/Unsafe Light(s) Illuminated, and Manual Gear Extension checklists with no success. Coordinated with maintenance and Boeing and still no success. Flight attendants and passengers briefed on possible emergency landing. Second and third gear confirmation made by TSA [Trans States Airline] aircraft, tower, and TWA maintenance on 2nd second fly by. Declared emergency. Went back to departure control and coordinated with TWA dispatch/maintenance/flight ops/ATC [Air Traffic Control] for emergency landing at BLV. Flight attendants were briefed to prepare the cabin for emergency landing. Passengers were briefed on what to expect.

A passenger, who was an Airframe and Powerplant mechanic, stated:

Passengers were told [at SPI] we would not disembark, but await fuel and weather.

About 1 1/2 hours later the aircraft was fueled and the captain said he had updated weather and we were going to be seated [and] get ready to depart.

Engine starts were normal [and] APU [auxiliary power unit] was retired.

At this point with engines running it seemed that it took a great deal of thrust to get the aircraft moving. I heard the hydraulics when breaks were released, but thought it unusual to use such thrust to get moving on a level ramp without a jet-way. The aircraft was simply pulling straight ahead. There were then two sharp jolts. I thought the P.I.C. [pilot in command] was checking his brakes, which I thought unusual.

Ground personnel at SPI received the diverted flight 519. One of the ground personnel stated:

There was no ground crew free at the time to flag out FLT 519 as I was busy and the other two agents were getting FLT 7637 boarded and it departed at 635P. After flagging out FLT 533 I went over to where FLT 519 had been sitting and discovered the chocks lying on the ramp.

The ramp where flight 519 was parked during its diversion was examined. A piece of cast metal debris was found on the ramp.

A cabin crewmember was asked for a statement to include the evacuation of the airplane at BLV and stated:

About 15 seconds after the aircraft stopped, the cockpit door was opened and I heard the captain say, 'Could I get some towels?' I opened the forward lavatory door got a handful of paper towels and handed them to the first officer.

Just then, I heard a loud noise as the R1 door was opened from the outside. The slide inflated. I saw about 3 or 4 firemen on the ground at the bottom of the slide. Then I heard the captain say again, 'Could I get some towels?' As I was handing him more towels, the L1 door was opened from the outside and the slide inflated. Again, I saw 3 or 4 fireman [at] the bottom of the slide.

By that time, the captain was out of his seat and said, 'Who opened that door?' I said, 'It was opened from the outside by fireman.' The captain then said, 'Alright, let's go.' The passengers were already in the aisle, ready to evacuate."

## DAMAGE TO AIRCRAFT

The operator reported that damage was "limited to lower skin of aircraft, [electrical and

National Transportation Safety Board

## FACTUAL REPORT

AVIATION

NTSB ID: CHI01FA270

Occurrence Date: 08/09/2001

Occurrence Type: Accident

## Narrative (Continued)

environmental] door, door frame, one area of lower rib around door."

## PERSONNEL INFORMATION

The operator reported that the captain held an airline transport pilot certificate with an airplane multiengine land rating. He held a first-class medical certificate with no limitations issued on May 29, 2001. The operator reported he had 12,845 hours total time and 318 hours in this make and model. The date of his last flight review was reported as June 29, 2001.

The operator reported that the first officer held a commercial certificate with an airplane multiengine land rating. He held a first-class medical certificate with limitations for corrective lenses issued on July 11, 2001. The operator reported he had 8,468 hours total time and 653 hours in this make and model. The date of his last flight review was reported as January 8, 2001.

## AIRCRAFT INFORMATION

The accident airplane, N2417F, was a Boeing 717-200, serial number 55084, twin engine, low-wing airplane with retractable tricycle landing gear. The airplane was powered by two fuselage mounted Rolls Royce BR700-715A1-30, 11,500 pounds of thrust, turbo fan engines. The operator reported that the airplane was inspected under a continuous inspection program and the airplane was last inspected on June 6, 2001. The airplane accumulated 45 hours of flight since that inspection and accumulated 845 hours total time. The operator reported that the airplane was configured to seat 7 crewmembers and 100 passengers. This airplane was not equipped with stairs.

## METEOROLOGICAL INFORMATION

At 1955, the BLV weather was: Wind 180 degrees at 6 knots; visibility 6 statute miles; present weather mist; sky condition broken 15,000 overcast 25,000; temperature 24 degrees C; dew point 23 degrees C; altimeter 29.91 inches of mercury.

## WRECKAGE AND IMPACT INFORMATION

An on-scene investigation was conducted. The nose of the airplane was raised. The nose landing gear (NLG) wheel well was examined. The left hand side of the NLG spray deflector assembly casting, marked as part number 5952241-501E, was found broken. The left hand support assembly, marked as part number 5961608-501A, was found with cast metal retained under two of the assembly's castellated nuts. This retained metal was similar in color to the cast metal that was found on the broken spray deflector assembly. The left hand support assembly and its vaned sideplate were found intact. That sideplate was found contacting the left hand side of the NLG wheel well. That sideplate and its support assembly were removed. The nlg was extended and it was found to go in its down and locked position. No other anomalies were observed.

The cast metal debris found on the SPI ramp where flight 519 was parked was similar in color to the broken spray deflector assembly. See appended photographs.

## TESTS AND RESEARCH

The debris found at SPI, the spray deflector assembly, and the left hand support assembly were sent to the National Transportation Safety Board's Materials Laboratory Division for detailed examination. The Materials Laboratory produced report 01-102 which is appended to this report.

 <p>National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION</p>	NTSB ID: CHI01FA270
	Occurrence Date: 08/09/2001
	Occurrence Type: Accident

## Narrative (Continued)

That report stated:

... The left support separated from the center portion of the deflector assembly ... . According to a diagram in the Boeing Illustrated Parts Catalog, a deflector assembly support is attached on the left and right side of the center portion of the deflector assembly. In the assembled condition, each side support is attached by two bolts and nuts to the center portion of the deflector assembly. The bolts are inserted into two through holes in the center portion. ...

Visual examination of the center portion revealed that pieces of the wall separated from areas around the through holes for the attachment bolts. Three pieces of the center portion were found secured between the attachment nuts and the wall of the support ... . A fourth fragment [identified as "M"] was found on the ramp of Springfield Airport, Springfield, Illinois, the airport from which the airplane had previously departed. No other piece fractured from the center portion of the deflector assembly.

Bench binocular microscope examination of the four fractured pieces revealed features typical of overstress separation in a casting. No evidence of a preexisting crack was found on the fractures. Scanning electron microscope examination of the separated pieces verified the overstress fractures features. X-ray energy dispersive spectroscopy analysis of piece "M" ... produced a spectrum that contained a major peak of aluminum, silicon, iron, and copper. The silicon peak was nearly 1/3 the height of the aluminum peak. The spectrum generated from piece "M" was consistent with one of several 3XX series aluminum alloy casting compositions.

The flight data recorders were reviewed by the operator. The operator's report on the four previous flight's data on engine pressure ratio (EPR) while the airplane started taxiing showed that the highest reading for EPR was on the third departure prior to the flight from SPI. That reading was 1.06 on the airplane's left engine and 1.04 on the right engine. The highest recorded EPR reading during the accident flight's taxi out was 1.08 on the left engine and 1.04 on the right engine. See appended operator's report. An excerpt from Section 20 "Taxi - Before Takeoff", in the Trans World Airlines 717 flight handbook, stated, "... Use equal thrust on both engines to start aircraft rolling. Keep engine thrust as low as possible when maneuvering in the ramp area. Maximum thrust without ground clearance is 1.1 EPR."

## ADDITIONAL INFORMATION

The parties to the investigation included the FAA, Trans World Airlines, Air Line Pilots Association, International, and Boeing.

The aircraft wreckage and retained parts were released to a representative of the operator.

A Boeing Flight Operations Bulletin, dated July 13, 2001, stated, "Several MD-80/B717 operators have reported incidents of Nose Landing Gear (NLG) spray deflector damage occurring when taxiing or operating over rigid military arresting gear."

Subsequent to the accident, a Boeing Flight Operations Bulletin, dated September 20, 2001, stated:

The purpose of this revision is to clarify and broaden the scope of this operations bulletin, to include possible damage to the NLG SPRAY DEFLECTOR caused by taxiing over a chock, striking a taxiway light or other obstruction, dropping the nosewheel into a pothole, etc. The consequences of such operation may result in damage to the NLG SPRAY DEFLECTOR that may prevent subsequent retraction or extension of the nose gear.

National Transportation Safety Board

**FACTUAL REPORT**

**AVIATION**

SAFETY BEYOND

NTSB ID: CHI01FA270

Occurrence Date: 08/09/2001

Occurrence Type: Accident

Narrative (Continued)

Subsequent to the accident, Boeing revised the 717 Flight Crew Operating Manual's taxi procedure to add the following caution note:

CAUTION: Taxiing over any surface obstruction, including arresting cables, may cause damage to the nosewheel spray deflector. Damage to the nosewheel spray deflector may cause the nosewheel to jam during extension or retraction. Therefore, avoid nosewheel contact with any obstruction, including arresting cables. If any contact is suspected with the nosewheel spray deflector, the nosewheel should be inspected prior to flight.

		NTSB ID: CHI01FA270			
		Occurrence Date: 08/09/2001			
		Occurrence Type: Accident			
Landing Facility/Approach Information					
Airport Name SCOTT AFB	Airport ID: BLV	Airport Elevation 459 Ft. MSL	Runway Used 14L	Runway Length 10000	Runway Width 150
Runway Surface Type: Concrete					
Runway Surface Condition: Wet					
Type Instrument Approach: Visual					
VFR Approach/Landing: Full Stop					
Aircraft Information					
Aircraft Manufacturer Boeing		Model/Series 717-200		Serial Number 55084	
Airworthiness Certificate(s): Transport					
Landing Gear Type: Retractable - Tricycle					
Homebuilt Aircraft? No	Number of Seats: 107	Certified Max Gross Wt. 118000 LBS	Number of Engines: 2		
Engine Type: Turbo Fan	Engine Manufacturer: Rolls-Royce	Model/Series: BR715-A1-30	Rated Power: 18500 LBS		
- Aircraft Inspection Information					
Type of Last Inspection Continuous Airworthiness	Date of Last Inspection 06/2001	Time Since Last Inspection 45 Hours	Airframe Total Time 845 Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed? No	ELT Operated? No	ELT Aided in Locating Accident Site? No			
Owner/Operator Information					
Registered Aircraft Owner MDFC Equipment Leasing Corporation		Street Address 3780 Kilroy Airport Way, Suite 750			
		City Long Beach	State	Zip Code 90806	
Operator of Aircraft TRANS WORLD AIRLINES		Street Address 11495 Natural Bridge Road			
		City Bridgeton	State MO	Zip Code 63044	
Operator Does Business As: Trans World Airlines			Operator Designator Code: TWAA		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): Flag Carrier/Domestic					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Part 121: Air Carrier					
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only					

 <p><b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b></p>	NTSB ID: CHI01FA270
	Occurrence Date: 08/09/2001
	Occurrence Type: Accident

**First Pilot Information**

Name On File	City On File	State On File	Date of Birth On File	Age 46
-----------------	-----------------	------------------	--------------------------	-----------

Sex: M	Seat Occupied: Left	Principal Profession: Civilian Pilot	Certificate Number: On File
--------	---------------------	--------------------------------------	-----------------------------

Certificate(s): Airline Transport

Airplane Rating(s): Multi-engine Land

Rotorcraft/Glider/LTA:

Instrument Rating(s): Airplane

Instructor Rating(s):

Type Rating/Endorsement for Accident/Incident Aircraft? Yes	Current Biennial Flight Review? 06/2001
---	---

Medical Cert.: Class 1	Medical Cert. Status: Valid Medical--no waivers/lim.	Date of Last Medical Exam: 05/2001
------------------------	--	------------------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	12845	318								
Pilot In Command(PIC)	6941	318								
Instructor										
Last 90 Days		204								
Last 30 Days		51								
Last 24 Hours		5								

Seatbelt Used? Yes	Shoulder Harness Used? Yes	Toxicology Performed? No	Second Pilot? Yes
--------------------	----------------------------	--------------------------	-------------------

**Flight Plan/Itinerary**

Type of Flight Plan Filed: IFR

Departure Point SPRINGFIELD	State IL	Airport Identifier SPI	Departure Time 1820	Time Zone CDT
--------------------------------	-------------	---------------------------	------------------------	------------------

Destination ST LOUIS	State MO	Airport Identifier STL	
-------------------------	-------------	---------------------------	--

Type of Clearance: IFR

Type of Airspace: Class D

**Weather Information**

Source of Briefing: Company

Method of Briefing: Aircraft Radio

 <p><b>National Transportation Safety Board</b> <b>FACTUAL REPORT</b> <b>AVIATION</b></p>	NTSB ID: CHI01FA270
	Occurrence Date: 08/09/2001
	Occurrence Type: Accident

**Weather Information**

WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
BLV	1955	CDT	459 Ft. MSL	0 NM	0 Deg. Mag.

Sky/Lowest Cloud Condition: \_\_\_\_\_ Ft. AGL      Condition of Light: Night/Dark

Lowest Ceiling: Broken      15000 Ft. AGL      Visibility: 6 SM      Altimeter: 29.91 "Hg

Temperature: 24 °C      Dew Point: 23 °C      Wind Direction: 180      Density Altitude: Ft.

Wind Speed: 6      Gusts:      Weather Conditions at Accident Site: Visual Conditions

Visibility (RVR): Ft.      Visibility (RVV) SM      Intensity of Precipitation:

Restrictions to Visibility: None

Type of Precipitation:

**Accident Information**

Aircraft Damage: Substantial      Aircraft Fire: None      Aircraft Explosion: None

Classification: U.S. Registered/U.S. Soil

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants				3	3
Other Crew					
Passengers				71	71
- TOTAL ABOARD -				76	76
Other Ground					
- GRAND TOTAL -				76	76

 <p>National Transportation Safety Board <b>FACTUAL REPORT</b> AVIATION</p>	NTSB ID: CHI01FA270
	Occurrence Date: 08/09/2001
	Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)  
Edward F. Malinowski

Additional Persons Participating in This Accident/Incident Investigation:

Pedro Rodriguez  
Inspector  
Federal Aviation Administration  
10801 Pear Tree Lane, Suite 250  
St. Ann, MO 63074

Noel B Wiebracht  
Field Service Representative  
Boeing  
P.O. Box 20126  
kansas City, MO 64195

Hugh Schoelzel  
Vice President - Corporate Safety  
Trans World Airlines, Inc.  
11495 Natural Bridge Road, Room 438  
Bridgeton, MO 63044