Wing collision with runway on landing, Boeing 727-2M7, August 30, 2004

Micro-summary: This Boeing 727-2M7's right wing collided with the runway while landing.

Event Date: 2004-08-30 at 1905 MDT

Investigative Body: National Transportation Safety Board (NTSB), USA

Investigative Body's Web Site: http://www.ntsb.gov/

Cautions:

- 1. Accident reports can be and sometimes are revised. Be sure to consult the investigative agency for the latest version before basing anything significant on content (e.g., thesis, research, etc).
- 2. Readers are advised that each report is a glimpse of events at specific points in time. While broad themes permeate the causal events leading up to crashes, and we can learn from those, the specific regulatory and technological environments can and do change. Your company's flight operations manual is the final authority as to the safe operation of your aircraft!
- 3. Reports may or may not represent reality. Many many non-scientific factors go into an investigation, including the magnitude of the event, the experience of the investigator, the political climate, relationship with the regulatory authority, technological and recovery capabilities, etc. It is recommended that the reader review all reports analytically. Even a "bad" report can be a very useful launching point for learning.
- 4. Contact us before reproducing or redistributing a report from this anthology. Individual countries have very differing views on copyright! We can advise you on the steps to follow.

Aircraft Accident Reports on DVD, Copyright © 2006 by Flight Simulation Systems, LLC All rights reserved.

www.fss.aero

National Transportation Safety Board NTSB ID: FTW04LA225 Aircraft Registration Number: N742RW FACTUAL REPORT Occurrence Date: 08/30/2004 Most Critical Injury: None **AVIATION** Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone El Paso TX 79925 1905 MDT Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Boeing 727-2M7 Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 30, 2004, approximately 1905 mountain daylight time, a Boeing 727-2M7 transport category airplane, N742RW, was substantially damaged when the right wing dragged the runway while landing at El Paso International Airport (ELP), El Paso, Texas. The airline transport rated captain, first officer and flight engineer were not injured. The airplane was owned by ART 21952 LLC, San Francisco, California, and operated by Custom Air Transport Incorporated, Fort Lauderdale, Florida. Visual meteorological conditions prevailed, and an instrument flight rules flight plan was filed for the 14 Code of Federal Regulations Part 121 cargo flight. The flight originated from the Chihuahua International Airport, Chihuahua, Mexico, at 1800 mountain daylight time, destined for El Paso International Airport, El Paso, Texas.

The 5,000-hour captain, of which 100 hours were in the same make and model of airplane, reported the 950-hour first officer, of which 650 hours were in make and model, was at the controls during the approach and initial touchdown of the airplane to runway 4 (a 12,010 foot long by 150 foot wide asphalt runway).

The flight crew further reported that during the final approach to landing, the airplane was right of the runway centerline and a left correction was initiated. The correction was "too severe," and the airplane overshot the runway centerline to the left. During the correction back to the right, the airplane bounced "hard." The captain then took the controls and completed a "safe" landing. The crew added that they were not aware that the right wing tip had struck the runway until after they exited the airplane.

According to a Federal Aviation Administration (FAA) inspector, who responded to the accident site, the right leading edge slat, right aileron, right flap, and right wing tip sustained structural damaged.

The digital flight data recorder was forwarded to the NTSB Vehicle Recorders Division, Washington, D.C., for readout, and the Boeing Company subsequently analyzed the data. The flight data recorder revealed that the airplane was approximately .6 nautical miles (NM) left of centerline approximately 1.6 NM from the runway threshold. The airplane continued to descend and correct in a right direction towards centerline. The right wing dragged the runway while the airplane was on a heading of 050 degrees and in a 19-degree right wing low bank-angle. The airplane then rolled to a left wing low bank-angle of 13 degrees. Subsequently the airplane's main landing gear touched down on the runway 2,150 feet beyond where the right wing dragged the ground.

At 1851 mountain daylight time, the weather observation facility at El Paso International Airport, El Paso, Texas, was reporting the wind from 140 degrees at 07 knots, visibility 10 statute miles, few clouds at 9,000 feet, temperature 84 degrees Fahrenheit, dew point 54 degrees Fahrenheit, and barometric pressure setting of 30.08 inches of Mercury.

NTSB ID: FTW04LA225

Occurrence Date: 08/30/2004

Occurrence Type: Accident

Narrative	(Continued)				

The NTSB investigator-in-charge calculated the density altitude at approximately 6,391 feet above sea level.

NTSB ID: FTW04LA225

Occurrence Date: 08/30/2004

AVIATION	Occurrence Type: Accident											
Landing Facility/Approach In	formation											
Airport Name	- Cimaton		Airport ID:	Airport Eleva	ition	Run	way Used	Runway Length		h F	Runwa	ay Width
EL PASO INTL			ELP	3958 Ft		04	·	1201	-		150	
Runway Surface Type: Asphalt												
Runway Surface Condition: Dry												
Runway Sunace Condition. Dry												
Type Instrument Approach: ILS-lo	calizer Only											
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer				el/Series						Number		
Boeing			727	-2M7					2195	2		
Airworthiness Certificate(s): Trans	port											
Landing Gear Type: Retractable	- Tricycle											
Homebuilt Aircraft? No	Homebuilt Aircraft? No Number of Seats: 3				Certified Max Gross Wt. 194800				LBS Number		of Engines: 3	
Engine Type: Turbo Jet			_	Engine Manufacturer: Model/Series: JT8D-15						Rated Power: 18000 LBS		
- Aircraft Inspection Information												
Type of Last Inspection			Date of Last Inspection Time Sin			Since Last Inspection			Airframe Total Time			
Continuous Airworthiness			11/2002	11/2002 1763 H				1763 Ho	lours 51251 Hours			51 Hours
- Emergency Locator Transmitter (ELT) Information											
ELT Installed? Yes	ELT Operat	ed? No)	ELT Aided in Locating Accident Site? No								
Owner/Operator Information												
Registered Aircraft Owner			Street Address 4 Embarcadero CTR FL 35									
ART 21952 LLC			City	City Sta								Zip Code
			San Francisco							СА		94111
Operator of Aircraft			Street Address 4101 Ravenswood Road									
·	NC		City State Zip Code									 Zip Code
CUSTOM AIR TRANSPORT INC				Ft. Lauderdale FI								33312
Operator Does Business As:	Operator Designator Code: C7WA											
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s)	Supplemental											
Operating Certificate:				Operator (Certific	ate:						
Regulation Flight Conducted Unde	r: Part 121: Air Ca	arrier		•								
Type of Flight Operation Conducted	: Non-scheduled	; Interr	national; C	argo								
		FACT	UAL REP	ORT - AVIAT	ION							Page 2

NTSB ID: FTW04LA225

Occurrence Date: 08/30/2004

AVIATION				Occurrence Type: Accident								
First Pilot	Information						,					
Name						City			State	Date of Birth	Age	
On File						On File		On File On File 4				
Sex: M	Seat Occupied:	Left	Pri	ncipal Profes	sion: Civiliar	n Pilot		Се	rtificate Nu	mber: On File	•	
Certificate(s): Airlin	e Transpor	t; Flight Eng	gineer								
Airplane Rating(s): Multi-engine Land												
Rotorcraft/Glider/LTA:												
Instrument Rating(s): Airplane												
Instructor Ra	ating(s): Instru	ument Airpl	ane									
Type Rating/Endorsement for Accident/Incident Aircraft? Yes Current Biennial Flight Review? 07/2004												
Medical Cer	t.: Class 1	Medica	al Cert. Status	s: Valid Med	dicalno wa	ivers/lim.		Date of L	ast Medical	Exam: 07/2004	1	
- Flight Time Matrix All A/C This Make and Model			Airplane Single Engine	Airplane Mult-Engine	Night	Inst Actual	rument Simulated	Rotorcra	ft Glider	Lighter Than Air		
Total Time		5000	100	600	4000	2000	480)				
Pilot In Com	mand(PIC)	1000	100	800	200	500	400)				
Instructor												
Last 90 Days	S	120	100	20		1						
Last 30 Days		100	100		100	80	8	3				
Last 24 Hou						<u> </u>						
Seatbelt Use	ed? Yes	Shou	lder Harness	Used? Yes		Toxico	ology Perfo	rmed? No		Second Pilot? Y	es	
Eli La Di	ne:											
Flight Plan												
	ht Plan Filed: IF	R				1					I	
Departure P						State		Airport Identifier Departure Time			Time Zone	
Chihuahua	ì						MO	CU	180	00	MDT	
Destination						State	Air	Airport Identifier				
El Paso				TX	EL	Р						
Type of Clea	arance: IFR					<u>'</u>						
Type of Airs	pace: Class	С										
Weather I	nformation											
Source of B												
Commercial Weather Service												
Method of B	Briefing: Teleph	ione										
				FACTUAL	REPORT -	- AVIATIO	N				Page 3	

NTSB ID: FTW04LA225

Occurrence Date: 08/30/2004

Occurrence Type: Accident

	FTYBON			,	710010011							
Weather	Information											
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Dis	WOF Distance From Accident Site					n Accident Site	Э
ELP	1851	MDT	3958 Ft.	MSL				NM			Deg.	Mag.
Sky/Lowes	st Cloud Condition: Few				6	0000 Ft. AG	3L	Condition o	f Ligh	nt: Day		
Lowest Ce	eiling: None		Ft.	AGL	Visibil	lity:	10	SM	Altii	meter:	30.08	"Hg
Temperatu	ure: 29 °C I	Dew Point:	12 °C	Wind I	Direction:	140			Der	nsity Altitude:	6391	Ft.
Wind Spee	ed: 7	Gusts:		Weather Condtions at Accident Site: Visual Conditions								
Visibility (R	RVR): Ft.	Visibility (R\	/V)	SM	Intensity	of Precipit	ation:					
Restriction	ns to Visibility: None											
Type of Pre	Type of Precipitation: None											
Accident	Information											
Aircraft Dar	mage: Substantial		Aircraft Fire	e: None				Aircraft Exp	losio	n None		
Classificati	ion: U.S. Registered/U	.S. Soil										
- Injury Su	mmary Matrix	Fatal Ser	rious Mino	ır	None	TOTAL						
First Pi	ilot				1	1	1					
Second	d Pilot				1	1	1					
Studen	nt Pilot						1					
Flight I	Instructor						1					
Check	Pilot						1					
Flight E	Engineer				1	1	1					
Cabin A	Attendants						1					
Other C	Crew						1					
Passen	ngers						1					
- TOTAL /	ABOARD -				3	3	1					
Other G	Ground						1					
- GRANE	D TOTAL -				3	3	1					

National Transportation Safety Board

FACTUAL REPORT AVIATION

Occurrence Date: 08/30/2004

Occurrence Type: Accident

	inist				

Investigator-In-Charge (IIC)

Frank McGill

Additional Persons Participating in This Accident/Incident Investigation:

Rob Soluren Aviation Safety Inspector Federal Aviation Administration 1601 Randolph Road SE, Suite 200N Albuquerque, NM 87106